

CITY OF LAGO VISTA

DEVELOPMENT SERVICES

5803 THUNDERBIRD SUITE 103 PO BOX 4727 LAGO VISTA, TX. 78645 Office: 512-267-5259 Fax: 512-267-5265

BACKFLOW PREVENTION ASSEMBLY TEST AND MAINTENANCE REPORT

	X	New Installation	☐ Annua	l Test	
		DEVELOPMENT	AGO VISTA, TX 78		
	OF SERVICE:		RIE RYED		
		operating within acc	as been tested and ma ceptable parameters. E OF ASSEMBLY	aintained as required	by commission
	Pressure Principle heck-Detector	Double Check V		ced Pressure Princip -Resistant Pressure V	
Manufacture Model Numb Serial Numb	er 85 0	· · L	ocated At Size	1 of Meter	3
Is the assemb	oly installed in accor	dance with manufac	cturer recommendation	ons and/or local code	s? YES
	Reduced Pressure Principle Assembly			Pressure Vacuum Breaker	
	Double Check	Valve Assembly		Air Inlet Check Valve	
,	1st Check	2nd Check	Relief Valve	All fillet	Check valve
Initial Test	Held at 2 , 2 psid Closed Tight 2 Leaked	Held at Z Ensid Closed Tight Z Leaked	Opened at psid Did not open □	Opened at psid Did not open 🏻 🗆	Held at psid Leaked □
Repairs and Materials Used					
Test Aster Repair	Held at psid Closed Tight □	Held at psid Closed Tight □	Opened at psid	Opened at psid	Held at psid
Remarks:	sed: Make/Model	10415T/ 845-3		314 Calibration Da	ale: 04/29/19
Firm Name:	certified to be true a SINCLAIR 312-56	SERVICES	Certified To	ester. Spc 75	Julas