CLWSC - Triple Peak - Backflow Prevention Assembly Test and Maintenance Report

The following form must be completed for each assembly tested for recordkeeping *purposes:

CLWSC - Triple Peak 0460172

P.O. Box 1742 **Contact Name:** Charlene Simmons Canyon Lake, Texas 78133 Phone Number: 830-312-4600

BPAT Information

Phone Number: **Company Name:** Safewater Backflow and Irrigation 5126059790

Brad Weyant Email Address: brad@safewateratx.com **Tester Name:** Address: 609 E 50TH License Number: BP0016935

AUSTIN, Texas 78751 License Expiration: 12/3/2024

Contact Information

Property Type: Residential Company Name:

TRI POINTE HOMES **Business Name:** Contact Name: **Property Address:**

1521 Escarpment **Mailing Address:** 16340 Park Ten PI ## 250 New Braunfels, TX 78132 Houston, TX 77084

Phone Number:

Email Address:

The backflow prevention assembly detailed below has been tested and maintained as required by commission regulations and is certified to be operating within acceptable parameters.

Backflow Method: Double Check Valve

Main Assembly Manufacturer: Febco Model: 850 Size: 1 Serial Number: HG02356

Location: Left front yard 5 feet from meter Hazard Type ****: Irrigation - Non Chemical

Test Result: Passed **New Installation** Reason for Test:

Is the assembly installed in accordance with manufacturers recommendations and/or local codes? Yes

Is the assembly installed on a non-potable water supply (auxiliary)? No

Differential pressure Midwest 845-5 (potable) Serial Number: 10150482 **Date Tested for Accuracy:** 10/7/2021

gauge used:

	Double Check Valve	
	Check Valve #1	Check Valve #2
Initial Test	Held at 1.9 PSID	Held at 2.2 PSID
Date: 5/6/2022	✓ ClosedTight	✓ ClosedTight
Time: 10:45 AM	Leaked	Leaked
Repairs and Materials Used		
Repair Details		
Test After Repairs	Held at 0 PSID	Held at 0 PSID
	Closed Tight	Closed Tight

Remarks

^{**} USE ONLY MANUFACTURER'S REPLACEMENT PARTS

^{*** 2}nd Check: Numeric reading required for double check valve only.

^{****} Indicates additional information not present on the standard TCEQ report