Service Address  * Backflow Prevention Assembly Test Report  Location: 42215  Backflow Prevention Assembly Test Report					
* SAN MARCOS, T	TX 78666	Location: 7 C   Meter#: 8 97 7 LID/Service: Account #:	%300 se	Prial #: Check if Correct  Anufacturer:	Corrections HFDZ4D5
Site Use: Hazard: Irr:, Mailing Address	O Ryne	Dak	Olv / si	odel:  pe:  ze:  ientation:	DCVA 1"
Protection:  Protection:  Protection:					
Test Due No Later than:    Existing					
	Reduced Pressure Principle Assembly  Double Check Valve Assembly			PVB/SVB	
	Check Valve #1	Check Valve #2	Relief Valve	Air Inlet	Check Valve
Initial Test Date 5/2/74 Time 10:43/A/7 Pass Atail	Leaked Closed Tight Held at PSID	Leaked Closed Tight Held at PSID	Did not open  Opened at PSID	Did not open Opened Fully Yes No Opened at PSID	Leaked  Held at PSID
Repairs  Date	Cleaned				
<b>Final Test</b> Date	Closed Tight	Closed Tight		Opened Fully	
Time Pass ☐Fail ☐	Held at PSID	Held at PSID	Opened at PSID	Opened at PSID	Held at PSID
Air Gap	Date	Time	Diameter	Separation	Pass
Comments:    Proper Installation   RV Exercised   R					
Company Safe		512 605	9790		Test Results ass X Fail
SAN MARCOS			[630 E F	HOPKINS ST	



Submit completed Test Report:

SAN MARCOS TX 78666 512-393-8008 Fax: SODONNELL@SANMARCOSTX.GOV