City of Georgetown - Backflow Prevention Assembly Test and Maintenance Report

The following form must be completed for each assembly tested for recordkeeping *purposes:

City of Georgetown PWS ID: 2460001

PO Box 1430 Contact Name: Water Regulatory Georgetown, Texas 78626 Phone Number: 512-930-3640

BPAT Information

Company Name:L Sinclair Services, Inc.Phone Number:512-563-8762Tester Name:Lewis SinclairEmail Address:Iss@austin.rr.comAddress:1307 Machado RoadLicense Number:BP0002815Cedar Park, Texas 78613License Expiration:2/12/2023

Location Information Contact Information

Property Type: Residential Company Name:

Business Name: Contact Name:

Property Address: 524 Calmo Ct Mailing Address: 524 Calmo Ct

Liberty Hill, TX 78642 Liberty Hill, TX 78642 Phone Number:

Email Address:

Backflow Information

The backflow prevention assembly detailed below has been tested and maintained as required by commission regulations and is certified to be operating within acceptable parameters.

Backflow Method: Double Check Valve

Main Assembly Manufacturer: Febco Model: 850 Size: 1 Serial Number: HG31059

Location: 5' ENE of meter

Hazard Type ****: Irrigation - Non Chemical

Backflow Test Information

Test Result: Passed
Reason for Test: New Installation

Is the assembly installed in accordance with manufacturers recommendations and/or local codes? Yes

Is the assembly installed on a non-potable water supply (auxiliary)? No

Differential pressure Bac-Flo 3 (potable) Serial Number: 03162474 Date Tested for Accuracy: 3/22/2022

gauge used:

	Double Check Valve	
	Check Valve #1	Check Valve #2
Initial Test	Held at 2.5 PSID	Held at 2.6 PSID
Date: 11/1/2022	✓ ClosedTight	✓ ClosedTight
Time: 1:10 PM	Leaked	Leaked
Repairs and Materials Used		
Repair Details		
Test After Repairs	Held at 0 PSID	Held at 0 PSID
	Closed Tight	Closed Tight

Remarks

^{**} USE ONLY MANUFACTURER'S REPLACEMENT PARTS

^{*** 2}nd Check: Numeric reading required for double check valve only.

^{****} Indicates additional information not present on the standard TCEQ report