City of Georgetown - Backflow Prevention Assembly Test and Maintenance Report

The following form must be completed for each assembly tested for recordkeeping *purposes:

City of Georgetown 2460001 PO Box 1430 **Contact Name:** Water Regulatory

Georgetown, Texas 78626 Phone Number: 512-930-3640

BPAT Information

Phone Number: **Company Name:** Safewater Backflow and Irrigation 5126059790

Brad Weyant Email Address: brad@safewateratx.com **Tester Name:** Address: 609 E 50TH License Number: BP0016935

AUSTIN, Texas 78751 License Expiration: 12/3/2024

Contact Information

Property Type: Residential **Company Name:**

Business Name: Contact Name: **Property Address:** 1312 Garrett Oaks Ln

Mailing Address: 1312 Garrett Oaks Ln Georgetown, TX 78633 Georgetown, TX 78633

Phone Number: **Email Address:**

The backflow prevention assembly detailed below has been tested and maintained as required by commission regulations and is certified to be operating within acceptable parameters.

Backflow Method: Double Check Valve

Main Assembly Manufacturer: Apollo Model: DC4A Size: 1 Serial Number: 01384D

Location: Right front yard 5 feet from meter Hazard Type ****: Irrigation - Non Chemical

Test Result: Passed New Installation Reason for Test:

Is the assembly installed in accordance with manufacturers recommendations and/or local codes? Yes

Is the assembly installed on a non-potable water supply (auxiliary)? No

Differential pressure MidWest 845-5 (potable) Serial Number: 09231317 **Date Tested for Accuracy:** 3/14/2024

gauge used:

	Double Check Valve	
	Check Valve #1	Check Valve #2
Initial Test	Held at 1.9 PSID	Held at 2.1 PSID
Date: 11/6/2024	✓ ClosedTight	✓ ClosedTight
Time: 11:10 AM	Leaked	Leaked
Repairs and Materials Used		
Repair Details		
Test After Repairs	Held at 0 PSID	Held at 0 PSID
	Closed Tight	Closed Tight

Remarks

^{**} USE ONLY MANUFACTURER'S REPLACEMENT PARTS

^{*** 2}nd Check: Numeric reading required for double check valve only.

^{****} Indicates additional information not present on the standard TCEQ report