City of Kyle - Backflow Prevention Assembly Test and Maintenance Report

The following form must be completed for each assembly tested for recordkeeping *purposes:

City of Kyle	**PWS ID:** 1050002
520 E RR 150	**Contact Name:** Mickal Morrison
Kyle, Texas 78640	**Phone Number:** 737-877-2927

BPAT Information

Company Name: Safety Plus Services, LLC.	**Phone Number:** 512-300-9659
Tester Name: Scott Stevenson	**Email Address:** scott@safetyplusservices.com
Address: 102 Wonder World Drive, Suite #304-522	**License Number:** BP0017507
San Marcos, Texas 78666	**License Expiration:** 12/19/2025

Location Information | Contact Information

Property Type: Residential	**Company Name:**
Business Name:	**Contact Name:**
Property Address: 202 Five Mile Creek Way	**Mailing Address:** 202 Five Mile Creek Way
Kyle, TX 78640	Kyle, TX 78640
	Phone Number:
	Email Address:

Backflow Information

The backflow prevention assembly detailed below has been tested and maintained as required by commission regulations and is certified to be operating within acceptable parameters.

Backflow Method: Double Check Valve

Main Assembly Manufacturer: Apollo **Model:** DC4A **Size:** 1 **Serial Number:** 64232C

Location: At Meter - Front Right

Hazard Type ****: Irrigation - Non Chemical

Backflow Test Information

Test Result: Passed

Reason for Test: New Installation

Is the assembly installed in accordance with manufacturers recommendations and/or local codes? Yes

Is the assembly installed on a non-potable water supply (auxiliary)? No

Differential pressure gauge used: BacFlo Unlimited Bac Flo 5 (potable) **Serial Number:** 06163433 **Date Tested for Accuracy:** 10/11/2023

	Double Check Valve	
	Check Valve #1	**Check Valve #2**
Initial Test Date: 6/18/2024 Time: 5:47 PM	Held at 2.2 PSID ☑ ClosedTight ☐ Leaked	Held at 2.2 PSID ☑ ClosedTight ☐ Leaked
Repairs and Materials Used		
Repair Details		
Test After Repairs	Held at 0 PSID ☐ Closed Tight	Held at 0 PSID ☐ Closed Tight

Remarks

The above is certified to be true at the time of testing.

* TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS [30 TAC 290.46(B)]

** USE ONLY MANUFACTURER'S REPLACEMENT PARTS

*** 2nd Check: Numeric reading required for double check valve only.

**** Indicates additional information not present on the standard TCEQ report