

4050 FM 1660 Hutto, Texas 78634 512-759-1286 Fax 512-759-2983

BACKFLOW PREVENTION ASSEMBLY TEST AND MAINTENANCE REPORT

PWS I.D: 2460022 MAILING ADDRESS_1000 Gurley Cv. Moose Rd. Hutto, TX 78634____

CONTACT PERSON _____ Taylor Morrison ____

LOCATION OF SERVICE_ 1000 Gurley Cv. Hutto, TX 78634_____

INSPECTION DATE ___9/15/2021 1:00 PM_____

The backflow prevention assembly detailed below has been tested and maintained as required by TCEQ regulations and is certified to be operating within acceptable parameters.

		TYPE OF ASS	EMBLY
()	Reduced Pressure ZONE	()	Reduced Pressure Principle-Detector
(X)	Double Check Valve	()	Double Check-Detector
()	Pressure Vacuum Breaker	()	Spill-Resistant Pressure Vacuum Breaker
Manu	ufacturer: Febco	_	
Mode	el # 850	Serial # HF75147	
Loca	tion of device Left front yard ne	ear meter	

Is the assembly installed in accordance with manufacturer recommendations and/or local codes? Yes_____

	Reduce	d Pressure Principle A	Pressure Vacuum Breaker				
	Double Check Va	ve Assembly	Relief Valve	Air Inlet	Check Valve		
	1st Check	2nd Check		Opened at psid	Held at psid		
Initial Test	Held at 1.9 psid	Held at 2.0 psid	Opened at psid	Did not Open 🛛	Leaked 🛛		
	Closed Tight X Leaked □	Closed Tight X Leaked □	Did not open □		-		
Repairs and Materials Used							
Test After	Held at ps Closed Tight D	id Held at psid Closed Tight □	Opened at psid	Opened at psid	Held At psid		
Repair							

The above is certified to be true at the time of testing,

Test gauge used: Make / Model Mid West 845_____ SN: 10150482_____ Calibration Date:10/9/2020____

Firm Name Safewater Backflow_____Certified Tester Brad Weyant___

Firm Address PO Box 4002 Austin, TX 78765

Cert. Tester No.BP0016935_____

Firm Phone # 512-605-9790

-	TEST	RECORDS	MUST	BE	KEPT	FOR	AT	LEAST	THREE	YEARS	**	USE	ONLY
MANUFACTURER'S REPLACEMENT PARTS													