

4050 FM 1660 Hutto, Texas 78634 512-759-1286 Fax 512-759-2983

BAC PWS I.D: 2460022	KFLOW PREVENT	ION ASSEMBLY	TEST AND MAINTI	ENANCE REPORT	
MAILING ADDRESS	206 Thurman Holt Rd.	Hutto, TX 78634		 	
CONTACT PERSON					
	VICE_ 206 Thurman Holt 9/8/2021 12:50 PM_				_
INOI ECHON DATE	9/0/2021 12:301 W_				,
	tion assembly detailed rating within acceptable		ed and maintained as	required by TCEQ regu	lations and
		TYPE OF	ASSEMBLY		
() Reduced Pressure ZONE () Reduced Pressure Principle-Detector					
(X) Double Check Valve			() Double Check-Detector		
() Press	ure Vacuum Breaker		() Spill-Resistant	Pressure Vacuum Bre	aker
Manufactur	er: Febco				
Model # 85	0	Serial # HF7620	2	_	
Location of	device Left front yard	near meter			
Is the assembly insta	illed in accordance with	manufacturer recom	nmendations and/or lo	cal codes? Yes	
	Reduced Pressure Principle As		sembly Pressure Vacuum Breaker		
	Double Check Valv	e Assembly	Relief Valve	Air Inlet	Check Valve
	1st Check	2nd Check		Opened at psid	Held at psid
Initial Test	Held at 2.1 psid	Held at 2.1 psid	Opened at psid	Did not Open □	Leaked 🗆
	Closed Tight X Leaked	Closed Tight X Leaked	Did not open		
Repairs and Materials Used					
Test After	Held at psic Closed Tight	Held at psid Closed Tight □	Opened at psid	Opened at psid	Held At psid
Repair					
The above is certif	ied to be true at the tim	e of testing,			
Test gauge used: N	Make / Model Mid Wes	t 845 SN: 1	0150482 Ca	alibration Date:10/9/202	20
Firm Name Safew	ater Backflow	Certified Teste	er Brad Weyant		
Firm Address PO	Box 4002 Austin, TX	78765	Cert. Tester N	o.BP0016935	
Firm Phone # 512	2-605-9790				

- TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS ** USE ONLY MANUFACTURER'S REPLACEMENT PARTS