

4050 FM 1660 Hutto, Texas 78634 512-759-1286 Fax 512-759-2983

BACKFLOW PREVENTION ASSEMBLY TEST AND MAINTENANCE REPORT

PWS I.D: 2460022

MAILING ADDRESS216 Thurman Holt Rd. Hutto, TX 78634								
CONTACT PERSONTaylor Morrison								
LOCATION OF SERVICE_ 216 Thurman Holt Rd. Hutto, TX 78634								
INSPECTION DATE9/8/2021 11:50 AM								

The backflow prevention assembly detailed below has been tested and maintained as required by TCEQ regulations and is certified to be operating within acceptable parameters.

		ITPE OF ASS	
()	Reduced Pressure ZONE	()	Reduced Pressure Principle-Detector
(X)	Double Check Valve	()	Double Check-Detector
()	Pressure Vacuum Breaker	()	Spill-Resistant Pressure Vacuum Breake
Manu	ufacturer: Febco		
Mode	el # 850	Serial # HF63274	
Loca	tion of device Right front yard r	near meter	

Is the assembly installed in accordance with manufacturer recommendations and/or local codes? Yes_____

	Reduced	Pressure Principle A	Pressure Vacuum Breaker				
	Double Check Val	e Assembly	Relief Valve	Air Inlet	Check Valve		
	1st Check	2nd Check		Opened at psid	Held at psid		
Initial Test	Held at 2.2 psid	Held at 2.5 psid	Opened at psid	Did not Open 🛛	Leaked 🗆		
	Closed Tight X Leaked □	Closed Tight X Leaked □	Did not open 🛛				
Repairs and Materials Used							
Test After	Held at psi Closed Tight □	d Held at psid Closed Tight □	Opened at psid	Opened at psid	Held At psid		
Repair							

The above is certified to be true at the time of testing,

Test gauge used: Make / Model Mid West 845_____ SN: 10150482_____ Calibration Date:10/9/2020____

Firm Name Safewater Backflow_____ Certified Tester Brad Weyant___

Firm Address PO Box 4002 Austin, TX 78765

Cert. Tester No.BP0016935_____

Firm Phone # 512-605-9790

-	TEST	RECORDS	MUST	BE	KEPT	FOR	AT	LEAST	THREE	YEARS	**	USE	ONLY
MANUFACTURER'S REPLACEMENT PARTS													

TYPE OF ASSEMBLY