

4050 FM 1660 Hutto, Texas 78634 512-759-1286 Fax 512-759-2983

PWS I.D: 2460022 MAILING ADDRESS CONTACT PERSON LOCATION OF SER	EKFLOW PREVENT 105 Thurman Holt Rd. 1 Taylor Morrison VICE 105 Thurman Holt 10/21/2021 1:00PM	Hutto, TX 78634t			-
	ntion assembly detailed rating within acceptabl		ed and maintained as	required by TCEQ regula	ations and
		TYPE OF	ASSEMBLY		
() Reduced Pressure ZONE			() Reduced Pressure Principle-Detector		
(X) Double Check Valve () Pressure Vacuum Breaker			Double Check-Detector Spill-Resistant Pressure Vacuum Breaker		
() Fless	die vacuum bleaker		() Spill-Resistan	i Flessule Vacuulli blea	Kei
Manufactur	er: Febco				
Model # 85	0	Serial # HF7737	70	_	
Location of	device Left front yard	d near meter			
Is the assembly insta	alled in accordance with	n manufacturer recon	nmendations and/or lo	cal codes? Yes	
	Reduced Pressure Principle Assembly Pressure Vacuum Breaker				
	Double Check Valv	ve Assembly	Relief Valve	Air Inlet	Check Valve
	1st Check	2nd Check		Opened at psid	Held at psid
Initial Test	Held at 1.9 psid	Held at 1.9 psid	Opened at psid	Did not Open	Leaked
	Closed Tight X Leaked	Closed Tight X Leaked	Did not open □		
Repairs and Materials Used					
Test After	Held at psic	d Held at psid Closed Tight □	Opened at psid	Opened at psid	Held At psid
Repair					
The above is certif	ied to be true at the tin	ne of testing,			
Test gauge used: I	Make / Model Mid Wes	st 845 SN: 10)150482 Ca	libration Date:10/7/2021	
Firm Name Safew	ater Backflow		Certified Tester: Brad Weyant		
Firm Address PO	Box 4002 Austin, TX	78765	Cert. Tester N	o: BP0016935	
Firm Phone # 512	2-605-9790				

- TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS ** USE ONLY MANUFACTURER'S REPLACEMENT PARTS