

4050 FM 1660 Hutto, Texas 78634 512-759-1286 Fax 512-759-2983

BACKFLOW PREVENTION ASSEMBLY TEST AND MAINTENANCE REPORT

MAILING ADDRESS CONTACT PERSON LOCATION OF SERV INSPECTION DATE	HIGHLAND	HOMES TURIN	LN.	MO,T	X 75022 - -	+		
	tion assembly detailed b		ed and maintair	ned as re	quired by TCE(2 regula	alions and	
is certified to be oper	rating within acceptable	parameters.						
() Reduced Pressure Principle Double Check Valve () Pressure Vacuum Breaker			ASSEMBLY () Reduced Pressure Principle-Detector () Double Check-Detector () Spill-Resistant Pressure Vacuum Breaker					
Model #	device: 31 K			d/or loca				
	Reduced Pressure Principle A				Pressure Vacuum Breaker			r
	Double Check Valve Assembly		Relief Valve		Air Inlet		Check Valve	
Initial Test	1st Check Held at 2, 2 osid	2nd Check Held at 20sid	Opened at	psid	Opened at Did not Open	psid	Held at Leaked	psid
	Closed Tight Leaked	Closed Tight Leaked	Did not open	а				
Repairs and Materials Used				-1				
Test After	Held at psid Closed Tight a	Held at psid Closed Tight o	Opened at	psid	Opened at	psid	Held At	psid
Firm Address	Make / Model BACFL HACLAIR SER BAIR PRIZIC	LIZES TY	Certified Tes	iter 12	4/01/2 00028	Zi Sel	3	
- TEST RECOI	RDS MUST BE KEI S ** USE ONLY TPARTS	PT FOR AT LEA						