Service Address	Hazard/CCID: 42215 Backflow Prevention Assembly Test Report				
*		Location: 3/9	Cololin	4 Jas	mine
SAN MARCOS, T	X 78666	anufacturer:	N 13 C 3 C 8 6 0		
Site Use: Hazard: Freightien/Lan				odel:	× 850
Mailing Address				/pe:	
319 Carolina Jusmine				ze:	× / /′
San Marcos/TX78666 Protection:					× Low Irrigation
Test Due No Later than: Existing Removed Commercial Industrial Residential Municipal Domestic Irrigation Fire					
	Reduced Press Double Check Val	sure Principle Ass ve Assembly	embly 	PVB/SVB	
	Check Valve #1	Check Valve #2	Relief Valve	Air Inlet	Check Valve
Initial Test Date 8/30/ Time <u>1:00 f/</u> Pass X Fail □	Leaked Closed Tight Held at PSID	Leaked Closed Tight Held at 2, 3 PSID	Did not open Opened at PSID	Did not open Opened Fully Yes No Opened at PSI	
Repairs Date Time	Cleaned				
Final Test Date	Closed Tight	Closed Tight		Opened Fully	
Time Pass	Held at PSID	Held at PSID	Opened atPSID	Opened at PS	ID Held at PSID
Air Gap	Date	Time	Diameter	Separation	_ Pass
Comments: Proper Installation RV Exercised #2 Shutoff Closed #2 Shutoff Closed Service Restored R					
Tester Big Virginity Signature Mby 9					
Certification # 500/6935 Expire 12/3/24 Phone 5/2 605 9795 Meter Reading 12/00/12/					
Test Kit Serial # 10150487 Calibration Date 10/7/2/ Test Results					
Company Safer ter Sackty Phone 5/2 605 9790 Pass X Fail					
Submit completed 630 E HOPKINS ST					



Test Report:

SAN MARCOS TX 78666 512-393-8008 Fax: SODONNELL@SANMARCOSTX.GOV