## City of Georgetown - Backflow Prevention Assembly Test and Maintenance Report

The following form must be completed for each assembly tested for recordkeeping \*purposes:

	City of Georgetown PO Box 1430 Georgetown, Texas 786	Box 1430			2460001 Water Regulatory 512-930-3640
			BPAT Inform	nation	
Company Name: Tester Name: Address:	Safewater Backflow and Brad Weyant 609 E 50TH AUSTIN, Texas 78751	E 50TH		one Number: ail Address: ense Number: ense Expiration:	5126059790 brad@safewateratx.com BP0016935 : 12/3/2024
	Location Informati	on			Contact Information
Property Type: Business Name: Property Address:	Residential 224 Dycus Bend Georgetown, TX 78628	Dycus Bend			224 Dycus Bend Georgetown, TX 78628
			Backflow Info	rmation	
The backflow preventior	assembly detailed below h	as been tested and	d maintained as re	quired by commis	ssion regulations and is certified to be operating within
Backflow Method: Main Assembly Manuf Location: Hazard Type ****:	Double Check acturer: Apollo Left front yard 5 feet fror Irrigation - Non Chemica	Model: n meter	DC4A Backflow Test Ir	Size: 1	Serial Number: 82479C
Test Result:	Passed		Backflow Test In	iformation	
Reason for Test:	New Installation				
Is the assembly install	ed in accordance with ma	nufacturers recon	nmendations and	/or local codes?	? Yes
Is the assembly install	ed on a non-potable wate	supply (auxiliary	')? No		
Differential pressure	MidWest 845-5 (potable)		Serial Number:	09231317	Date Tested for Accuracy: 3/14/2024
gauge used:		Double Check Valve			
	Check V		Check Valve	e #2	
Initial Test Date: 5/23/2024 Time: 4:10 PM	Held at 1.9 PSID	н	eld at 2 PSID ClosedTight Leaked		
Repairs and Materials Used	1				
Repair Details					
Test After Repa	irs Held at 0 PSID		eld at 0 PSID		
		I	Remark	(S	

The above is certified to be true at the time of testing. \* TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS [30 TAC 290.46(B)] \*\* USE ONLY MANUFACTURER'S REPLACEMENT PARTS \*\*\* 2nd Check: Numeric reading required for double check valve only. \*\*\*\* Indicates additional information not present on the standard TCEQ report