	City	y of Georgetown - Ba	ckflow Preventic	on Assembly Test a	and Maintenance Report
he following form must	be compl	eted for each assembly teste	ed for recordkeeping *	purposes:	
	PO Bo	Georgetown x 1430 etown, Texas 78626		PWS ID: Contact Name: Phone Number:	2460001 Water Regulatory 512-930-3640
			BPAT Ir	oformation	
Company Name: Fester Name: Address:	Lewis : 1307 N	air Services, Inc. Sinclair Machado Road Park, Texas 78613		Phone Number: Email Address: License Number: License Expiration:	512-563-8762 Iss@austin.rr.com BP0002815 2/12/2026
	Loc	ation Information			Contact Information
Property Type: Business Name: Property Address:		rcus Bend Hill, TX 78642		Company Name: Contact Name: Mailing Address: Phone Number: Email Address:	241 Dycus Bend Liberty Hill, TX 78642
			Backflow	Information	
Backflow Method: Main Assembly Manuf Ocation: Hazard Type ****:	7' E of		Model: DC4A	Size: 1	Serial Number: 53574C
			Backflow Te	est Information	
est Result: Reason for Test: s the assembly install		d stallation ordance with manufacture	rs recommendations	s and/or local codes? \	/es
s the assembly install	led on a n	on-potable water supply (a			
Differential pressure auge used:	Bac-Fl	o Bac-Flo 3 (potable)	Serial Numl	ber: 03162474	Date Tested for Accuracy: 3/16/2023
		Double Check Valve			
Initial Test		Check Valve #1 Held at 1.7 PSID	Check Held at 2.3 PS	Valve #2	
Date: 10/12/2023 Time: 12:20 PM		ClosedTight Leaked	ClosedTigh		
Repairs and Materials Use	d				
Repair Details					

	Check Valve #1	Check Valve #2	
Initial Test	Held at 1.7 PSID	Held at 2.3 PSID	
Date: 10/12/2023	✓ ClosedTight	✓ ClosedTight	
Time: 12:20 PM	Leaked	Leaked	
Repairs and Materials Used			
Repair Details			
Test After Repairs	Held at 0 PSID	Held at 0 PSID	
	Closed Tight	Closed Tight	

^{*} TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS [30 TAC 290.46(B)]

^{**} USE ONLY MANUFACTURER'S REPLACEMENT PARTS

^{*** 2}nd Check: Numeric reading required for double check valve only.

^{****} Indicates additional information not present on the standard TCEQ report