City of Georgetown - Backflow Prevention Assembly Test and Maintenance Report

The following form must be completed for each assembly tested for recordkeeping *purposes:

City of Georgetown 2460001

PO Box 1430 **Contact Name:** Water Regulatory Georgetown, Texas 78626 **Phone Number:** 512-930-3640

BPAT Information

Company Name: Safewater Backflow and Irrigation

Phone Number: 5126059790 **Brad Weyant Email Address:** brad@safewateratx.com **Tester Name:** 609 E 50TH BP0016935 Address: License Number:

AUSTIN, Texas 78751

Contact Information

12/3/2024

Residential **Company Name:**

Property Type: Business Name: Contact Name:

132 Pipe Cactus Pass **Property Address: Mailing Address:** 132 Pipe Cactus Pass Georgetown, TX 78633 Georgetown, TX 78633

Phone Number: **Email Address:**

License Expiration:

Backflow Information

The backflow prevention assembly detailed below has been tested and maintained as required by commission regulations and is certified to be operating within acceptable parameters.

Backflow Method: Double Check Valve

Main Assembly Manufacturer: Apollo Model: DC4A Size: 1 Serial Number: 85645C

Location: Left front yard 5 feet from meter Hazard Type ****: Irrigation - Non Chemical

Backflow Test Information

Test Result: Passed **New Installation** Reason for Test:

Is the assembly installed in accordance with manufacturers recommendations and/or local codes? Yes

Is the assembly installed on a non-potable water supply (auxiliary)? No

Differential pressure MidWest 845-5 (potable) Serial Number: 09231317 Date Tested for Accuracy: 3/14/2024

gauge used:

	Double Check Valve	
	Check Valve #1	Check Valve #2
Initial Test	Held at 2 PSID	Held at 2.2 PSID
Date: 8/12/2024	✓ ClosedTight	✓ ClosedTight
Time: 9:35 AM	Leaked	Leaked
Repairs and Materials Used		
Repair Details		
Test After Repairs	Held at 0 PSID	Held at 0 PSID
	Closed Tight	Closed Tight

Remarks

^{**} USE ONLY MANUFACTURER'S REPLACEMENT PARTS

^{*** 2}nd Check: Numeric reading required for double check valve only.

^{****} Indicates additional information not present on the standard TCEQ report