
City of Leander - PWSID #2460012

Backflow Prevention Assembly Test and Maintenance Report





Customer / Property Name: Resident PWS Contact Name: Jeff Tucker
Contact Name: N/A PWS Phone Number: (512) 528-2780
Property Address: PWS Address: PO Box 319

Leander, TX 78641-5929

Leander, TX, 78646

The backflow prevention assembly detailed below has been tested as required by TCEQ regulations and is certified to be operating within acceptable parameters.

Assembly Information

Type:DCModel #:DC4ASize:1"Serial#:98153CManufacturer:ApolloBPA Serves:Irrigation

Location: 4' SSE of Water Meter

Reason for test: [] new [X] existing [] replaced.

Is the assembly installed in accordance with manufacturer recommendations and/or local codes? [X] yes [] no

Water supply: Potable

Assembly Test Information

Initial Test (Time: 02:30 pm)	
Check Valve #1: 0.0	Check Valve #2: 0.0
() Closed Tight/Held (X) Leaked	() Closed Tight/Held (X) Leaked
Final Test (Time: 02:45 pm)	
Final Test (Time: 02:45 pm)	
Final Test (Time: 02:45 pm) Check Valve #1: 1.6	Check Valve #2 : 1.7

Additional comments or repairs made / materials (parts) used:

Remove rocks and Teflon tape from both check valves & flush.

As the tester of record, I affirm this test as: Passed [X] Failed [] Repairs Made:** Yes

Tester Information

Tester Name: Sinclair, Lewis
Tester License Expiration: 02-12-2026
Certification#: BP0002815
Test Kit Serial #: 10200408
Test Kit Date Tested for Accuracy: 02-28-2024

Test Kit Mfr. & Mod. #: Mid-West 845-5 (Potable)
Testing Co Name: L Sinclair Services Inc.

Phone: (512) 563-8762

Address: 1307 Machado Road Cedar Park, TX 78613

The above tester certifies that all information submitted for this report is true and accurate

The backflow prevention assembly detailed above has been tested and maintained as required by commission regulations and is certified to be operating within acceptable parameters

Test Date: 2024-11-26

^{*} TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS [30 TAC §290.46(B)]

^{**} USE ONLY MANUFACTURER'S REPLACEMENT PARTS