City of Georgetown - Backflow Prevention Assembly Test and Maintenance Report

The following form must be completed for each assembly tested for recordkeeping *purposes:

City of Georgetown 2460001 PO Box 1430 **Contact Name:** Water Regulatory Georgetown, Texas 78626 Phone Number: 512-930-3640

BPAT Information

Company Name: Safewater Backflow and Irrigation

Brad Weyant Tester Name: Address:

609 E 50TH AUSTIN, Texas 78751 Phone Number: 5126059790

Email Address: brad@safewateratx.com

License Number: BP0016935 License Expiration: 12/3/2024

Contact Information

Property Type: Residential **Company Name: Business Name:** Contact Name:

Property Address: 204 Jim Bowie Dr **Mailing Address:**

204 Jim Bowie Dr Georgetown, TX 78628 Georgetown, TX 78628

Phone Number:

Email Address:

The backflow prevention assembly detailed below has been tested and maintained as required by commission regulations and is certified to be operating within acceptable parameters.

Backflow Method: Reduced Pressure Principle

Main Assembly Manufacturer: Febco Model: 860 Size: 1 Serial Number: HA27155

Location: Left front yard 10 feet from meter Hazard Type ****: Irrigation - Non Chemical

Test Result: Passed

Reason for Test: **Existing Installation**

Is the assembly installed in accordance with manufacturers recommendations and/or local codes? Yes

Is the assembly installed on a non-potable water supply (auxiliary)? No

Differential pressure MidWest 845-5 (potable) Serial Number: 09231317 **Date Tested for Accuracy:** 3/14/2024

gauge used:

	Reduced Pressure Principle		
	Check Valve #1	Check Valve #2	Relief Valve
Initial Test	Held at 7.5 PSID	Held at PSID	Opened at 2.4 PSID
Date: 11/13/2024 Time: 10:35 AM	✔ ClosedTightLeaked	✔ ClosedTightLeaked	Did not open
Repairs and Materials Used			
Repair Details			
Test After Repairs	Held at 0 PSID Closed Tight	Held at PSID Closed Tight	Opened at 0 PSID

Remarks

^{**} USE ONLY MANUFACTURER'S REPLACEMENT PARTS

^{*** 2}nd Check: Numeric reading required for double check valve only. **** Indicates additional information not present on the standard TCEQ report