City of Georgetown - Backflow Prevention Assembly Test and Maintenance Report

The following form must be completed for each assembly tested for recordkeeping *purposes:

	City of Georgetown	PWS ID:		2460001
	PO Box 1430 Georgetown, Texas 78626	Contact Nam Phone Numb		Water Regulatory 512-930-3640
		BPAT Information		
Company Name: Tester Name: Address:	Safewater Backflow and Irrigation Brad Weyant 609 E 50TH AUSTIN, Texas 78751	Phone Numb Email Addre: License Num License Expi	ss: nber:	5126059790 brad@safewateratx.com BP0016935 12/3/2024
	Location Information			Contact Information
Property Type: Business Name: Property Address:	Residential 304 Great Lawn Bend Georgetown, TX 78628	Company Na Contact Nam Mailing Addr Phone Numb Email Addres	ne: ress: per:	304 Great Lawn Bend Georgetown, TX 78628
		Backflow Information		
The backflow prevention acceptable parameters.	assembly detailed below has been t	tested and maintained as required by	commission re	egulations and is certified to be operating within
Backflow Method: Main Assembly Manufa Location: Hazard Type ****:	Double Check Valve cturer: Apollo Left front yard 5 feet from meter Irrigation - Non Chemical	Model: DC4A Size	e: 1	Serial Number: 88555C
		Backflow Test Information	on	
Test Result: Reason for Test:	Passed New Installation			
-		ers recommendations and/or local	codes? Yes	
Differential pressure	ed on a non-potable water supply (MidWest 845-5 (potable)	(auxiliary)? No Serial Number: 092313	17	Date Tested for Accuracy: 3/14/2024
gauge used:		uble Check Valve		
	Check Valve #1	Check Valve #2		
Initial Test Date: 8/5/2024 Time: 1:20 PM	Held at 2.1 PSID	Held at 2.2 PSID		
Repairs and Materials Used				
Repair Details				
Test After Repai	rs Held at 0 PSID	Held at 0 PSID		
		Remarks		

The above is certified to be true at the time of testing. * TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS [30 TAC 290.46(B)] ** USE ONLY MANUFACTURER'S REPLACEMENT PARTS *** 2nd Check: Numeric reading required for double check valve only. **** Indicates additional information not present on the standard TCEQ report