City of Georgetown - Backflow Prevention Assembly Test and Maintenance Report

The following form must be completed for each assembly tested for recordkeeping *purposes:

	City of Georgetown PO Box 1430	PWS ID: Contact Name:	2460001 Water Regulatory
	Georgetown, Texas 78626	Phone Number:	
		BPAT Information	
Company Name: Fester Name: Address:	Safewater Backflow and Irrigation Brad Weyant 609 E 50TH AUSTIN, Texas 78751	n Phone Number: Email Address: License Numbe License Expirat	brad@safewateratx.com r: BP0016935
	Location Information		Contact Information
Property Type: Business Name: Property Address:	Residential 441 Wolf Ridge Rd Georgetown, TX 78628	Company Name Contact Name: Mailing Address Phone Number: Email Address:	s: 441 Wolf Ridge Rd Georgetown, TX 78628
		Backflow Information	
he backflow prevention cceptable parameters.	assembly detailed below has been	tested and maintained as required by con	nmission regulations and is certified to be operating within
Backflow Method: Aain Assembly Manufa .ocation: Iazard Type ****:	Double Check Valve acturer: Apollo Right front yard 5 feet from meter Irrigation - Non Chemical	Model: DC4A Size:	1 Serial Number: 64233C
		Backflow Test Information	
est Result: Reason for Test:	Passed New Installation		
-		ers recommendations and/or local cod	les? Yes
s the assembly installe Differential pressure auge used:	ed on a non-potable water supply MidWest 845-5 (potable)	(auxiliary)? No Serial Number: 09231317	Date Tested for Accuracy: 3/14/2024
-	Do	uble Check Valve	
	Check Valve #1	Check Valve #2	
Initial Test Date: 6/26/2024 Fime: 9:45 AM	Held at 2.1 PSID ClosedTight Leaked	Held at 2 PSID ClosedTight Leaked	
Repairs and Materials Usec			
Repair Details		·	
Test After Repai	rs Held at 0 PSID	Held at 0 PSID	
		Remarks	J

The above is certified to be true at the time of testing. * TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS [30 TAC 290.46(B)] ** USE ONLY MANUFACTURER'S REPLACEMENT PARTS *** 2nd Check: Numeric reading required for double check valve only. **** Indicates additional information not present on the standard TCEQ report