## New Braunfels Utilities - Backflow Prevention Assembly Test and Maintenance Report

The following form must be completed for each assembly tested for recordkeeping \*purposes:

	New Braunfels Utilities 2356 Gruene Rd. New Braunfels, Texas 78130		ID: act Name: ne Number:	0460001 James Garvin 830-312-8098	
		BPAT Inform	ation		
Company Name: Tester Name: Address:	Safewater Backflow and Irrigatic Brad Weyant 609 E 50TH AUSTIN, Texas 78751	Emai Licer	ne Number: il Address: nse Number: nse Expiration:	5126059790 brad@safewateratx.com BP0016935 12/3/2024	
	Location Information			Contact Information	
Property Type: Business Name: Property Address:	Residential 5725 Huron Dr New, TX 78130	Cont Maili Phor	pany Name: act Name: ng Address: ne Number: il Address:	5725 Huron Dr New Braunfels, TX 78130	
		Backflow Infor	mation		
The backflow prevention acceptable parameters.	assembly detailed below has beer	tested and maintained as requ	uired by commission	on regulations and is certified to be operating within	
Backflow Method: Main Assembly Manuf Location: Hazard Type ****:	Double Check Valve acturer: Apollo Right front yard 5 feet from mete Irrigation - Non Chemical	<b>Model:</b> DC4A ar	Size: 1	Serial Number: 88862C	
		Backflow Test Inf	ormation		
Test Result: Reason for Test:	Passed New Installation				
	ed in accordance with manufactu		or local codes?	Yes	
-	ed on a non-potable water supply				
Differential pressure gauge used:	MidWest 845-5 (potable)	Serial Number:	09231317	Date Tested for Accuracy: 3/14/2024	
33	Do	ouble Check Valve			
	Check Valve #1	Check Valve	#2		
Initial Test Date: 7/8/2024 Time: 11:15 AM Repairs and Materials Used	Held at 2.1 PSID	Held at 1.9 PSID			
Repair Details		•			
Test After Repa	irs Held at 0 PSID	Held at 0 PSID			
		Remarks	S		

The above is certified to be true at the time of testing. \* TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS [30 TAC 290.46(B)] \*\* USE ONLY MANUFACTURER'S REPLACEMENT PARTS \*\*\* 2nd Check: Numeric reading required for double check valve only. \*\*\*\* Indicates additional information not present on the standard TCEQ report