

Spike O Jonahuster. com

4050 FM 1660 Hutto, Texas 78634

Doodle Ln

PWS I.D: 2460022

MAILING ADDRESS 305

512-759-1286 Fax 512-759-

BACKFLOW PREVENTION ASSEMBLY TEST AND MAINTENANCE REPORT

ONTACT PERSON	Taylor Morrisor	1	• • • • • • • • • • • • • • • • • • • •			
DCATION OF SERVISPECTION DATE	10/17/72	ch				
SPECTION DATE	10)11/03					
ne backflow prevent certified to be oper	tion assembly detailed brating within acceptable	pelow has been teste parameters.	ed and maintained as re	quired by TCEQ regula	ations and	
		TYPE OF	ASSEMBLY			
() Reduc	ced Pressure Principle	TIPLOF	() Reduced Pressure	Principle-Detector		
Double Check Valve () Double Check-Detector						
() Press	ure Vacuum Breaker		() Spill-Resistant F	ressure Vacuum Brea	ker	
	Apple					
Manufactur	er: Apollo					
Model #_	DC4A device: 10' Lef	Serial # 57997	С			
	10' 1-0	1 0 1 1				
Location of	device : 10 Cet	t of meach		===		
the assembly insta	alled in accordance with	manufacturer recom	nmendations and/or loca	al codes? Yes		
the assembly moto		Pressure Principle A		Pressure Vac	uum Breaker	
	Double Check Valve Assembly		Relief Valve	Air Inlet	Check Valve	
	1st Check	2nd Check		Opened at psid	Held at psid	
Initial Test		Held at 1,5 psid	Opened at psid	Did not Open 11	Leaked n	
	Closed Tight	Closed Tight	Did not open a			
	Leaked	Leaked 11				
Repairs and		<u> </u>				
Materials Used						
			Opened at psid	Opened at psid	Held At psid	
Test After	Closed Tight n	Closed Tight				
Repair						
	ied to be true at the tim	e of testina.				
	Make / Model Works		1907 Calibratian Date	1/19/23	§	
l est gauge used: I	Make / Model	10-110SN. 311	Calibration Date	mana Misse	TI lan	
Firm Name HZF	Antiers Trl. Le	refer	Certified Lester / M.C	mas Morey) Lange of the same of the sam	
	Antiers Tri, Lea X, 78641		Cert. Tester No.	0016285		
Firm Phone # Cc	512) 259-5296					
- TEST RECOF	RDS MUST BE KE	PT FOR AT LEA	AST			
THREE YEARS	S ** USE ONLY	MANUFACTURE	R'S			
REPLACEMENT		200 SESTORS & TO TO THE	公 战 范			
	as as vaccinational constant					



Spike & Jonahuster, com

4050 FM 1660 - Hutto, Texas 78634 - 2983

Doodle Ln

PWS I.D: 2460022

MAILING ADDRESS 307

512-759-1286 Fax 512-759-

BACKFLOW PREVENTION ASSEMBLY TEST AND MAINTENANCE REPORT

CONTACT PERSON LOCATION OF SERV INSPECTION DATE	MCE 307 Dood!	e in				
The backflow prevent is certified to be open	tion assembly detailed b rating within acceptable	elow has been teste parameters.	ed and maintained as re	quired by TCEQ regula	ations and	
		TYPE OF	ASSEMBLY			
() D-d	and Deceases Dringinla	I THE OF	() Reduced Pressure	Principle-Detector		
() Reduced Pressure Principle () Reduced Pressure Principle-Detector () Double Check Valve () Double Check-Detector						
() Press	ker					
Manufacture	er: Apollo					
Model#_0	OCYA 5 device : 7' R131	Serial # _ 5287	5C			
455	71 011	01 00 10	1 -			
Location of	device : / K 15	nt of ma	her	=		
le the accomply insta	lled in accordance with	manufacturer recom	mendations and/or loca	al codes? TeS		
13 the assembly moto		Pressure Principle A		Pressure Vac	uum Breaker	
	Double Check Valve Assembly		Relief Valve	Air Inlet	Crieck valve	
	1st Check	2nd Check		Opened at psid	Held at psid	
Initial Test		Held at Z.o psid	Opened at psid	Did not Open 1	Leaked m	
	Closed Tight Leaked	Closed Tight A Leaked 11	Did not open 11			
Repairs and Materials Used						
Test After	Held at psid Closed Tight n	Held at psid Closed Tight 11	Opened at psid	Opened at psid	Held At psid	
Repair	12.					
The above is certifi	ied to be true at the time	e of testing,				
	Make / Model WH+S 7		1997 Calibration Date	1/19/23	ø	
Firm Name H2F	Clar.	70 770 SIV. 2 - 1	Cortified Tester The	mas morey	The Same	
Firm Name // CP	Antiers Trl, Leo	nder			1	
Firm Address 7	x, 78641		Cert. Tester No. DF	0016285		
Firm Phone # Cc	512) 259-5296					
- TEST RECOF	RDS MUST BE KEF	PT FOR AT LEA	IST			
THREE YEARS	S ** USE ONLY I	MANUFACTURE	R'S			
REPLACEMENT	T PARTS					