# City of Georgetown - Backflow Prevention Assembly Test and Maintenance Report

The following form must be completed for each assembly tested for recordkeeping \*purposes:

City of Georgetown 2460001

PO Box 1430 **Contact Name:** Water Regulatory Georgetown, Texas 78626 Phone Number: 512-930-3640

### **BPAT Information**

Phone Number: **Company Name:** Safewater Backflow and Irrigation

5126059790 **Brad Weyant Email Address:** brad@safewateratx.com **Tester Name:** Address: 609 E 50TH License Number: BP0016935

AUSTIN, Texas 78751 License Expiration: 12/3/2024

**Contact Information** 

**Property Type:** Residential **Company Name: Business Name:** Contact Name:

**Property Address:** 1325 Salt Lick Dr **Mailing Address:** 1325 Salt Lick Dr

Georgetown, TX 78633 Georgetown, TX 78633

Phone Number: **Email Address:** 

The backflow prevention assembly detailed below has been tested and maintained as required by commission regulations and is certified to be operating within acceptable parameters.

**Backflow Method: Double Check Valve** 

Main Assembly Manufacturer: Apollo Model: DC4A Size: 1 Serial Number: 85550C

Location: Left front yard 5 feet from meter Hazard Type \*\*\*\*: Irrigation - Non Chemical

**Test Result:** Passed New Installation Reason for Test:

Is the assembly installed in accordance with manufacturers recommendations and/or local codes? Yes

Is the assembly installed on a non-potable water supply (auxiliary)? No

Differential pressure MidWest 845-5 (potable) Serial Number: 09231317 **Date Tested for Accuracy:** 3/14/2024

gauge used:

	Double Check Valve	
	Check Valve #1	Check Valve #2
Initial Test	Held at 2.1 PSID	Held at 2.3 PSID
Date: 6/5/2024	✓ ClosedTight	✓ ClosedTight
Time: 12:00 PM	Leaked	Leaked
Repairs and Materials Used		
Repair Details		
Test After Repairs	Held at 0 PSID	Held at 0 PSID
	Closed Tight	Closed Tight

## Remarks

<sup>\*\*</sup> USE ONLY MANUFACTURER'S REPLACEMENT PARTS

<sup>\*\*\* 2</sup>nd Check: Numeric reading required for double check valve only.

<sup>\*\*\*\*</sup> Indicates additional information not present on the standard TCEQ report