p.1

Texas Commission on Environmental Quality BACKFLOW PREVENTION ASSEMBLY TEST AND MAINTENANCE REPORT

TH

The following form must be completed for each assembly tested. A signed and dated original must be submitted to the public water supplier for recordkeeping *purposes:

NAME OF PWS:		C	City of Leander							
PWS ID#:			2460012							
MAILING ADDRESS:		P	PO Box 319 Leander, TX 78646							
CONTACT PERSON:			Christi Williams							
LOCATION OF SERVICE:			4113 Novella Cove							
and is certific	ed to be ope	erating w	bly detailed below has been tested and maintained as required by commission regular within acceptable parameters. Reduced Pressure Principle Double Check Valve Double Check-Detector							
				☐ Double Check-Detector						
		LJ P	ressure Vacuum Br	□ Spill-F	☐ Spill-Resistant Pressure Vacuum Breaker					
Manufacture	r: Febo				Size:	127	122			
Model Number: 850			· · · · · · · · · · · · · · · · · · ·		Located At					$\neg \neg$
Serial Number	er: HE	322	3 <i>t</i> s							
Is the assembly installed in accordance with manufacturer recommendations and/or local codes? ☑ Yes ☐ No										
	Reduced F	Pressure	Principle Assembly			Pressu	Pressure Vacuum Breaker			
Double Che-		e Check	Valve Assembly					[
			2 nd Check	Reli	ef Valve	Air Inlet		Check Valve		
Initial Test	Held at 2.1 psi Closed Tight 5 Leaked		Held at Z psid Closed Tight X Leaked	Opened at ps Did not open [Opened at Did not open	_psid	Held at _ Leaked	psid	
Repairs and Materials Used**										
Test After Repair	Held at Closed Tig	-	Held at psid	Opened	at psid	Opened at	_psid	Held at	psid	
Test gauge used: Make/Model: Midwest / 845-3 SN: 06111314 Date tested for accuracy: 06/01/2017 Remarks: Residential Irrigation The above is certified to be true at the time of testing.										
Firm Name: L Sincl			air Services Inc. Certified Tester Name (Print/Type): Lewis R. Sinclair							
Firm Address:		Cedar Park, TX 78613		Certified Tester Name (Signature):						
Firm Phone #: 512-563-8762 Cert. Tester No.: BP0002815 Date of Test: 12/04/17										/17
+ mnom n = =	ODD 0.15								- -	•

^{*} TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS

^{**} USE ONLY MANUFACTURER'S REPLACEMENT PARTS