NAME OF PWS:

p.3

Texas Commission on Environmental Quality BACKFLOW PREVENTION ASSEMBLY TEST AND MAINTENANCE REPORT

The following form must be completed for each assembly tested. A signed and dated original must be submitted to the public water supplier for recordkeeping *purposes:

City of Leander

PWS ID#:		2460012							
MAILING A	ADDRESS:	PO Box 319 Leander	r, TX 786	46					
CONTACT	PERSON:	Christi Williams							
LOCATION	OF SERVICE: 4	4221 Vespa Cove							
The backflow	w prevention assented to be operating	ably detailed below l within acceptable pa	has been t rameters.	ested and ma	aintained as require	ed by commis	sion regulati	ions	
TYPE OF A	SSEMBLY:	Reduced Pressure Pr	rinciple		☐ Reduced 1	Pressure Princ	ciple-Detecto	or	
☑ Double Check			•		☐ Double Check-Detector				
☐ Pressure Vacuum Bro				reaker					
Manufacture	r: Febco				1"		7		
Model Numb	per: 850			Located At	: 25 WS	VI OF	OF METER		
Serial Numb	er: HE3Z	274.					1		
Is the assemb	F	ordance with manufa		commendation				1	
	Reduced Pressure Principle Assemb				Pressure Vacuum Breaker				
	Double Check	Valve Assembly 2nd Check Reli		ef Valve	Air Inlet	Chec	Check Valve		
T 141 1 20 4		 							
Initial Test	Closed Tight Leaked	Held at Z spsid Closed Tight Z Leaked	Opened Did not	at psid open	Opened atp Did not open		psid		
Repairs and Materials Used**									
Test After Repair	Held at psid Closed Tight □	Held at psid Closed Tight □	Opened	at psid	Opened atp	sid Held at	psid		
Test gauge us									
Make/Model	: Midwest / 845	-3 SN: 06	111314	D	ate tested for accur	racy: 06/01/	2017		
Remarks:							00000		
Residential In	rigation					,			
	·	The above is cert	ified to b	e true at the	time of testing.				
Firm Name:	L Sinclai	r Services Inc. (Certified Tester Name (Print/Type): Lewis R. Sinclair						
							-		
Firm Phone #: 512-50			Cert. Test		****	ate of Test:	12/04	717	
* TEST REC	ORDS MUST BE	KEPT FOR AT LEA	AST THR	EE YEARS		, ,		1	

^{**} USE ONLY MANUFACTURER'S REPLACEMENT PARTS