Test and Maintenance Report

Water System ID# 2270001

Special Services Division
3907 South Industrial DR
Austin, TX 78744-1070

Phone: (512) 972-1060
FAX: (512) 972-1260

*** Test records must be kept by the customer for at least three years ***

Backflow Assembly Information

Serial Number:	HE40637	**Manufacturer:**	FEBCO
Model:	850	**Size:**	1

Service Address:	6200 BERNIA DR 78652
Assembly location on the property:	7' NORTH-NORTHEAST OF METER.
Reason the assembly is installed:	IRRIGATION W/ CITY POTABLE WATER
Is this assembly installed to code requirements?	Yes

Customer Information

Property Owner / Agent:	CALATLANTIC HOMES
Mailing Address:	11001 LAKELINE BLVD. BLDG. 1, STE. 100
City / State / Zip:	AUSTIN, TX 78717
Phone:	(512) 506-4000

Backflow Test

	DCVA	
Initial Test	**Check Valve #1**	**Check Valve #2**
	2.8 PSID	2.9 PSID
Repairs		
Test After Repairs		

Test Date:	Nov 22, 2017
Backflow Test Status:	Passed

Tester Information

The backflow technician listed below has previously certified that the information on this report was true and correct on the date of this test.

Backflow Technician:	SINCLAIR, LEWIS R

License:	BP0002815
Gauge Serial Number:	06111314