

Test and Maintenance Report

Water System ID# 2270001

Special Services Division 3907 South Industrial DR Austin, TX 78744-1070

Phone: (512) 972-1060 FAX: (512) 972-1260



*** Tcs	t records must be kept by	the customer for at least th	ree years *:	**
	Backflow Ass	embly Information	***	
Serial Number:	HE50608	Manufactu	ırer:	FEBCO
Model:	850	Size:		1
Service Address:		11906 BAY HEIGHTS WAY 78726		
Accombly location on the property:		8' NORTHEAST OF METER.		
Reason the assembly is installed:		IRRIGATION W/ CITY POTABLE WATER		
Is this assembly installed to code requirements?		Yes		
	Custome	r Information	The state of the s	
Property Owner / Agent:		TAYLOR MORRISON HOMES		
Mailing Address:		11200 LAKELINE BLVD. STE. 150A		
City / State / Zip:		AUSTIN, TX 78717		
Phone:		(512) 328-8866		
	Back	flow Test		
	DCVA			
Initial Test	Check V	alve #1	Check Valve #2	
	2.7 1	PSID	2.6 PSID	
Repairs				
Test After Repairs				
Test Date:		Feb 15, 2018		
Backflow Test Status:		Passed		
	Tester :	Information		
The backflow technician li	sted below has prev was true and correc	viously certified that t t on the date of this t	the inforn	nation on this repor
Rackflow Tee	hnicianı	CINCLAID LEWIC	Ъ	

Backflow Technician:

SINCLAIR, LEWIS R

Гер 15 10, 04:52р

L Sinclair Services Inc.

5122597479

p.3

WEIRS - Backflow Prevention Assembly Test Details

Page 2 of 2

License:	BP0002815	
Gauge Serial Number:	06111314	