



# Backflow Prevention Assembly Test and Maintenance Report

NAME OF PWS: REUNION RANCH  
 PWS I.D. #: 1050175  
 MAILING ADDRESS: 11700 LAKELINE BLVD, STE 150A, AUSTIN, TX 78717  
 CONTACT PERSON: TAYLOR MERRISON  
 LOCATION OF SERVICE: 306 JACKSDAW DR

The backflow prevention assembly detailed below has been tested and maintained as required by TCEQ regulations and is certified to be operating within acceptable parameters.

**TYPE OF ASSEMBLY**

- Reduced Pressure Principle
- Double Check Valve
- Pressure Vacuum Breaker
- Reduced Pressure Principle-Detector
- Double Check-Detector
- Spill-Resistant Pressure Vacuum Breaker

Manufacturer FEBZD Size 1"  
 Model Number 850 Located At 2 1/2 S OF HIGHWAY  
 Serial Number HE 24646

Is the assembly installed in accordance with manufacturer recommendations and/or local codes? YES

	Reduced Pressure Principle Assembly			Pressure Vacuum Breaker	
	Double Check Valve Assembly		Relief Valve	Air Inlet	Check Valve
	1st Check	2nd Check		Opened at ___ psid	Held at ___ psid
Initial Test	Held at <u>2.7</u> psid Closed Tight <input checked="" type="checkbox"/> Leaked <input type="checkbox"/>	Held at <u>2.3</u> psid Closed Tight <input checked="" type="checkbox"/> Leaked <input type="checkbox"/>	Opened at ___ psid Did not open <input type="checkbox"/>	Did not open <input checked="" type="checkbox"/>	Leaked <input checked="" type="checkbox"/>
Repairs and Materials Used					
Test After Repair	Held at ___ psid Closed Tight <input checked="" type="checkbox"/>	Held at ___ psid Closed Tight <input checked="" type="checkbox"/>	Opened at ___ psid	Opened at ___ psid	Held at ___ psid

Test gauge used: Make/Model MIDWEST/845-3 SN: 06111314 Calibration Date: 02/01/17

Remarks:

The above is certified to be true at the time of testing.

Firm Name L SINCLAIR SERVICES INC. Certified Tester Christina Sinclair  
 Firm Address CEDAR PARK, TX 78613 Cert. Tester No. B30002815 Date 02/19/18  
 Firm Phone # 512-563-8762

\*TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS.