

## Backflow Prevention Assembly Test and Maintenance Report

NAME OF PWS: RELIAION RANGE					
PWS I.D. #: 1050175					
MAILING ADDRESS: 11700 LAKELINE BLUD, STE ISOA, AUSTIN, TX 795117					
CONTACT PERSON: TAYLOR MERRISON					
LOCATION OF SERVICE: 771 JACKSDAW DR.					
The backflow prevention assembly detailed below has been tested and maintained as required by TCEQ regulations and is certified to be operating within acceptable parameters.  TYPE OF ASSEMBLY  Reduced Pressure Principle  Double Check Valve  Double Check Valve  Pressure Vacuum Breaker  Reduced Pressure Principle-Detector  Double Check-Detector  Spill-Resistant Pressure Vacuum Breaker					
Manufacturer_FEBCOSize					
Manufacturer FEBCO SIZE Located At 7'NE OF METER					
Serial Number HESOL77					
Is the assembly installed in accordance with manufacturer recommendations and/or local codes?					
Reduced Pressure Principle Assembly			Pressure Vacuum Breaker		
Double Check Va				Air Inlet	Check Valve
	1st Check	2nd Check	Relief Valve	Opened at psid	Held at psid
Initial Test	Held at 2.2 psid Closed Tight 2. Leaked	Held at 2 psid Closed Tight Leaked	Opened atpsid  Did not open	Did not open 🚨	Leaked 🖪
Repairs and Materials Used					
Test After Repair	Held atpsid	Held at psid	Opened atpsid	Opened atpsid	Held at psid
	Closed Tight	Closed Tight			0.4.4.7
Test gauge used: Make/Model MIDNEST/245-3 SN: OCI11314 Calibration Date: OG/O1/17 Remarks:					
The above is certified to be true at the time of testing.					
Firm Name LSINCLAIR SERVICES INC. Certified Tester June 1900/1815 Date 07/14/18 Firm Address CEDAIZ FARK, TX 78613 Cert. Tester No. BPOUCES Date 07/14/18					
Firm Phone # 512-563-6762					
*TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS.					
TEGI MECONDO MOGI DE BUX I I OTOTA DE LA CONTRE DELIGIO DE LA CONTRE DELIGIO DE LA CONTRE DE LA					