



CITY OF LAGO VISTA DEVELOPMENT SERVICES

Office: 512-267-5259
Fax: 512-267-5265

5803 THUNDERBIRD SUITE 103
PO BOX 4727 LAGO VISTA, TX. 78645

BACKFLOW PREVENTION ASSEMBLY TEST AND MAINTENANCE REPORT

New Installation Annual Test

NAME OF PWS: CITY OF LAGO VISTA
 PWS I.D.: # 2270092
 MAILING ADDRESS: P.O. BOX 4727, LAGO VISTA, TX 78645
 CITY CONTACT PERSON: DEVELOPMENT SERVICES

PROPERTY OWNER'S NAME: DREAM FINDERS
 LOCATION OF SERVICE: 2813 HANCOCK AVE.

The backflow prevention assembly detailed below has been tested and maintained as required by commission regulations and is certified to be operating within acceptable parameters.

TYPE OF ASSEMBLY

Reduced Pressure Principle Double Check Valve Reduced Pressure Principle-Detector
 Double Check-Detector Pressure Vacuum Breaker Spill-Resistant Pressure Vacuum Breaker

Manufacturer FERCO Size 1"
 Model Number 450 Located At 7' NE OF METER
 Serial Number HE36779

Is the assembly installed in accordance with manufacturer recommendations and/or local codes? YES

	Reduced Pressure Principle Assembly			Pressure Vacuum Breaker	
	Double Check Valve Assembly			Air Inlet	Check Valve
	1st Check	2nd Check	Relief Valve		
Initial Test	Held at <u>2.2</u> psid Closed Tight <input checked="" type="checkbox"/> Leaked <input type="checkbox"/>	Held at <u>2.2</u> psid Closed Tight <input checked="" type="checkbox"/> Leaked <input type="checkbox"/>	Opened at _____ psid Did not open <input type="checkbox"/>	Opened at _____ psid Did not open <input type="checkbox"/>	Held at _____ psid Leaked <input type="checkbox"/>
Repairs and Materials Used					
Test After Repair	Held at _____ psid Closed Tight <input type="checkbox"/>	Held at _____ psid Closed Tight <input type="checkbox"/>	Opened at _____ psid	Opened at _____ psid	Held at _____ psid

Test gauge used: Make/Model MIDWEST/845-3 SN: 0611314 Calibration Date: 02/01/17
 Remarks: NONE

The above is certified to be true at the time of testing.

Firm Name: LSINCLAIR SERVICES INC Certified Tester: L. Sinclair
 Firm Phone #: 512-503-2702 Cert. Tester No: EP000215 Date: 03/02/18
 Firm Address: MAJADO CEDAR PARK, TX 78613