

L Sinclair Services Inc.

Backflow Prevention Assembly Test and Maintenance Report

NAME OF PWS: HAYS COUNTY WCID # Z					
PWS I.D. #: 1050148					
MAILING ADDRESS: 4761 W. PARMER LN. BULDINGB, SLUTETED, AUSTIN TX 78727					
CONTACT PERSON: HIGHLAND HOMES					
LOCATION OF SERVICE: 146 MEDINA HIUS CT.					
The backflow prevention assembly detailed below has been tested and maintained as required by TCEQ regulations and is certified to be operating within acceptable parameters. TYPE OF ASSEMBLY Reduced Pressure Principle Reduced Pressure Principle Double Check Valve Double Check-Detector Pressure Vacuum Breaker Spill-Resistant Pressure Vacuum Breaker					
Manufacturer FEECO Size					
Manufacturer FEECO Size Model Number 550 Located At 6' SSE OF METER					
Serial Number 1+E44961					
Is the assembly installed in accordance with manufacturer recommendations and/or local codes?					
Reduced Pressure Principle Assembly Pressure Vacuum Breaker					
	Double Check Valve Assembly			Air Inlet	Check Valve
	1st Check	2nd Check	Relief Valve	Opened at psid	
Initial Test	Held at 2. esid Closed Tight Sy Leaked	Held at Z 2 peid Closed Tight Leaked	Opened at psid Did not open •	Did not open 🚨	Leaked 🖪
Repairs and Materials Used					
Test After Repair	Held at psid	Held at psid	Opened at psid	Opened atpsid	Held at psid
	Closed Tight 🖪	Closed Tight			
Test gauge used: Make/Model MIDWEST/845-3 SN: OCILI314 Calibration Date: OC/OI/17 Remarks:					
The above is certified to be true at the time of testing. Firm Name LSINCLAIR SERVICES INC. Certified Tester Two Rounds Date D3/19/15 Firm Address CEDAIZ FARK TX 78613 Cert. Tester No. BP00072815 Date D3/19/15					
Firm Phone # 51Z-563-6762					
*TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS.					

14050 Summit Dr. • Austin, TX 78728 • (512) 246-0498 • Fax (512) 716-0024