



CITY OF LAGO VISTA DEVELOPMENT SERVICES

5803 THUNDERBIRD SUITE 103
PO BOX 4727 LAGO VISTA, TX. 78645

Office: 512-267-5259

Fax: 512-267-5265

BACKFLOW PREVENTION ASSEMBLY TEST AND MAINTENANCE REPORT

New Installation

Annual Test

NAME OF PWS: CITY OF LAGO VISTA
PWS I.D.: # 2270092
MAILING ADDRESS: P.O. BOX 4727, LAGO VISTA, TX 78645
CITY CONTACT PERSON: DEVELOPMENT SERVICES

PROPERTY OWNER'S NAME: HIGHLAND HOMES
LOCATION OF SERVICE: 7908B SUNRISE RAVINE PASS

The backflow prevention assembly detailed below has been tested and maintained as required by commission regulations and is certified to be operating within acceptable parameters.

TYPE OF ASSEMBLY

- Reduced Pressure Principle Double Check Valve Reduced Pressure Principle-Detector
 Double Check-Detector Pressure Vacuum Breaker Spill-Resistant Pressure Vacuum Breaker

Manufacturer FEBCO Size 1"
Model Number B50 Located At 6" NW OF METER
Serial Number HE49435

Is the assembly installed in accordance with manufacturer recommendations and/or local codes? YES

	Reduced Pressure Principle Assembly			Pressure Vacuum Breaker	
	Double Check Valve Assembly			Air Inlet	Check Valve
	1st Check	2nd Check	Relief Valve		
Initial Test	Held at <u>2.5</u> psid Closed Tight <input checked="" type="checkbox"/> Leaked <input type="checkbox"/>	Held at <u>2.5</u> psid Closed Tight <input checked="" type="checkbox"/> Leaked <input type="checkbox"/>	Opened at _____ psid Did not open <input type="checkbox"/>	Opened at _____ psid Did not open <input type="checkbox"/>	Held at _____ psid Leaked <input type="checkbox"/>
Repairs and Materials Used					
Test After Repair	Held at _____ psid Closed Tight <input type="checkbox"/>	Held at _____ psid Closed Tight <input type="checkbox"/>	Opened at _____ psid	Opened at _____ psid	Held at _____ psid

Test gauge used: Make/Model MIDWEST/845-3 SN: 06111314 Calibration Date: 06/01/17

Remarks: NONE

The above is certified to be true at the time of testing.

Firm Name: L SINCLAIR SERVICES Certified Tester: L Sinclair
Firm Phone #: 512-563-8162 Cert. Tester No.: 3900075615 Date: 03/14/18
Firm Address: CEDAR PARK, TX 78613