Texas Commission on Environmental Quality

MERIT

BACKFLOW PREVENTION ASSEMBLY TEST AND MAINTENANCE REPORT

| The following form must | be completed for | each asser | nbly tester | d. A signe | d and da | ted original must be | submitte | d to the public water supplier | Tor recording purposes | |
|--|--|-------------------------------------|--------------|--------------------------------|--|---|----------------------|--------------------------------|---------------------------------------|--|
| NAME OF PWS: | | City c | f Roun | d Rock | | | | | | |
| PWS ID#: | : 201 W. D1-1 #100 Pound Rock TV 78664 | | | | | | | | | |
| PWS MAILING AI | v. Bago | . Bagdad #100, Round Rock, TX 78664 | | | | | | | | |
| PWS CONTACT P | Inspection Dept 512-218-5550 | | | | | | | | | |
| ADDRESS OF SERVICE: 838 Kenney Fort Crossing The backflow prevention assembly detailed below has been tested and maintained as required by commission regulations | | | | | | | | | | |
| The backflow prev | ention assem | ibiy del | aneu bi | ble para | meter | t toptod and m | | | | |
| and is certified to be operating within acceptable parameters. TYPE OF BACKFLOW PREVENTION ASSEMBLY (BPA): | | | | | | | | | | |
| Dodugod Pre | Deduced Pressure Principle-Detector (KPDA-D) | | | | | | | | | |
| | P. V (2 C - 2 - 7 C | | | Double Check-Detector (DCVA-D) | | | | | | |
| | | | | | pill-Resistant Pressure Vacuum Breaker (SVB) | | | | | |
| ☐ Pressure Va | cuum Break | er (PVE | \$) | | Spin-1 | CSIStant 1 TCSS | - Turk | Outili Di Outili (e) | | |
| Manufacturer: | Febco | | | | | Size: | | 1 22 | | |
| Model Number: 850 | | | | | BPA Location: By W BE METER | | | | | |
| Serial Number: HE32737 | | | | | BPA Serves: Residential Landscap | | | e Irrigation | | |
| Serial Tuttiber: | | | | | | | | | | |
| Reason for test: New 🗵 Existing 🗆 Replacement 🗆 Old Model/Serial # | | | | | | | | | | |
| Reason for test: New \(\) Existing \(\) Replacement \(\) Old Model/Serial # Is the assembly installed in accordance with manufacturer recommendations and/or local c | | | | | | | | or local codes? | ☑ Yes ☐ No | |
| is the assembly ins | taried in acco | n dance | hlo met | an allac | iv (ar | viliary)? | | | ☐ Yes ☑ No | |
| Is the assembly installed on a non-potable water supply (auxiliary)? | | | | | | | | | | |
| | Reduced Pre | DCVA st Check 2nd Check*** | | | | bly (RPBA) Relief Valve | | PVB & SVB | | |
| | | | | | | | | Air Inlet | Check Valve | |
| | | | | | | | | | | |
| | 1st Chee | | | | | | | | | |
| Initial Test | Held at 2. | psid | Held at | 29 | | | psid | | Held atpsid | |
| Date 23/14/12 | | | | | 又 | Did not open | | Did not open □ Leaked □ | | |
| Time: 1ZAOF1 | I caked | | | | | | | | | |
| LATORE | | 3 | | | l | | | Did it fully open | | |
| | | | | | 1 | er <u></u> | | (Yes □ /No □) | | |
| Danaira and | | | <u> </u> | | | | | | | |
| Repairs and Materials Used** | | | | | | | | | | |
| Materials Oscu | | | | | | | | | | |
| | <u> </u> | | <u> </u> | | | Onemadiat | neid | Opened atpsic | i Held at psid | |
| Test After | Held at | | | | - 6 | | | Opened at por | | |
| Repair | Closed Tigl | nt 🗀 | Closed Tight | | ╵╏ | | | | | |
| Date: | | | | | | | | | | |
| Time: | www ond -l- | -1 | | ading re | ouire | d for DCVA o | nlv | <u> </u> | | |
| D:66 | | | ici ic re | aumg 10 | E | otable: | | Non-Potable | | |
| 5-8 | | | | | | 06111314 Date tested for accuracy: 06/01/2017 | | | | |
| Make/Model: | Midwest / 84 | 3-3 | | 1 2311 | 100 | | | | | |
| Remarks. | None | | 3 2 2 | | | | | | | |
| | | | | | | | | | · · · · · · · · · · · · · · · · · · · | |
| | · · · · · · · · · · · · · · · · · · · | | | | | · · | | | | |
| Company Name: I. Sinclair Services Inc. Licensed Tester Name (Print/Type): Lewis R. Sinclair | | | | | | | | | | |
| Company Addre | Park, TX 78613 | | | Lice | Licensed Tester Name (Signature): | | | | | |
| Company Phone | | 63-876 | | | | AT License # | | BP0002815 | | |
| | | | | | Lic | ense Expiratio | n Date: | 02/12/2020 | THE COLUMN TO STATE OF | |
| | | 9930.738 | | | 8 | 4 41. a 42 F 4 | anti | | TEST RESULT | |
| 50 \$513920000000 00000000 00000000000000000000 | The abo | ve is c | ertified | to be t | rue a | t the time of t | s a tau . esmilă• | TAC 8290 46(B)] | PASS 🙎 | |
| * TEST RECOR | DS MUST E | SE KEI | T FOR | AT LE | ASI MENU | ITENCE IEAU PARTS | vo loo | TAC §290.46(B)] | FAIL 🗆 | |
| ** USE ONLY | VLANUFAC | IUKE | COREP | LACE | ا 14 انتلا4 | | | | 300 951 | |