

## Backflow Prevention Assembly Test Details



## Test and Maintenance Report

Water System ID# 2270001

Special Services Division  
3907 South Industrial DR  
Austin, TX 78744-1070

Phone: (512) 972-1060  
FAX: (512) 972-1260



\*\*\* Test records must be kept by the customer for at least three years \*\*\*

## Backflow Assembly Information

<b>Serial Number:</b>	HE75266	<b>Manufacturer:</b>	FEBCO
<b>Model:</b>	850	<b>Size:</b>	1
<b>Service Address:</b>	2205 INDIAN TRL 78703		
<b>Assembly location on the property:</b>	10' SOUTH-SOUTHEAST OF METER.		
<b>Reason the assembly is installed:</b>	IRRIGATION W/ CITY POTABLE WATER		
<b>Is this assembly installed to code requirements?</b>	Yes		

## Customer Information

<b>Property Owner / Agent:</b>	JOSEPH BUILDERS
<b>Mailing Address:</b>	1107 S 8TH STREET
<b>City / State / Zip:</b>	AUSTIN, TX 78704
<b>Phone:</b>	(512) 850-8974

## Backflow Test

Initial Test	DCVA	
	Check Valve #1	Check Valve #2
	2.8 PSID	2.9 PSID

## Repairs

## Test After Repairs

<b>Test Date:</b>	Mar 4, 2019
<b>Backflow Test Status:</b>	Passed

## Tester Information

The backflow technician listed below has previously certified that the information on this report was true and correct on the date of this test.

<b>Backflow Technician:</b>	SINCLAIR, LEWIS R
<b>License:</b>	BP0002815
<b>Gauge Serial Number:</b>	06111314

Day

Edit

Delete

**\*2205 Indian trail (irrigation) PERMITTED**

Thursday, February 21, 2019 12:00 AM

Friday, February 22, 2019 12:00 AM

Created by Jason Stubblefield

**Description**

Joseph Bldrs - Austin 78703

03/04

1" FEB 850 ✓

HE 75266 ✓

#1 - 2.8

#2 - 2.9

10' SSE OF MTD

Manage accounts

bestoftexaslandscape@gmail.com

Settings

[Help & Terms](#)

View: **Mobile** | [Desktop](#)

©2010 Google