



Travis County Water Control and Improvement District No. 17

3812 Eck Lane · Austin, Texas 78734

**Water and Wastewater Utility Cross Connection Section
Test and Maintenance Report**

Date: 03/20/19

Residential



Commercial



New Installation



- leave test report on device

Annual Test



- fax results

Semiannual Test



- fax results

Results must be submitted within 5 days. Illegible or incomplete reports will not be accepted.

Backflow Assembly Information		Please Print	
Serial Number:	<u>944491</u>	Manufacturer:	<u>APOLLO</u>
Occupant/Business Name:	Model:		<u>RP4A</u>
Physical Address:	Size:		<u>1"</u>
Assembly Location on Property:	<u>RIGHT SIDE OF HOUSE BEHIND PLANTER</u>		
Reason the assembly is installed:	<u>LANDSCAPE IRRIGATION</u>		

TYPE OF ASSEMBLY:



Reduced Pressure Principle



Double Check Valve



Pressure Vacuum Breaker



Reduced Pressure Principle-Detector



Double Check - Detector



Spill-Resistant Pressure Vacuum Breaker

	Reduced Pressure Principle Assembly			Pressure Vacuum Breaker	
	Double Check Valve Assembly		Relief Valve	Air Inlet	Check Valve
	1st Check	2nd Check			
Initial Test	Held at <u>8.4</u> psid Closed Tight <input checked="" type="checkbox"/> Leaked <input type="checkbox"/>	Held at <u>—</u> psid Closed Tight <input checked="" type="checkbox"/> Leaked <input type="checkbox"/>	Opened at <u>4.7</u> psid Did not open <input type="checkbox"/>	Opened at <u>—</u> psid Did not open <input type="checkbox"/>	Held at <u>—</u> psid Leaked <input type="checkbox"/>
Repairs and Materials Used					
Test After Repair	Held at <u>—</u> psid Closed Tight <input type="checkbox"/>	Held at <u>—</u> psid Closed Tight <input type="checkbox"/>	Opened at <u>—</u> psid	Opened at <u>—</u> psid	Held at <u>—</u> psid

The above is certified to be true? YES

Is this assembly installed in accordance with Local Codes? YES

FINAL BACKFLOW TEST STATUS

(Pass) / Fail

Test gauge used: Make/Model MIDWEST/8453 SN: 06111314

Calibration Date: 05/14/18

Remarks: NONE

Company Name: L SINGULAR SERVICES

Backflow Technician (print) LEWIS R. SINGULAR

Address: CEDAR PARK, TX 78613

Certified Tester (Signature) [Signature]

Phone #: 512-563-8762

Cert. Tester No. BPO002815

Fax completed form: (annual/semiannual only)

Residential (512) 266-2790

Commercial: (512) 266-4871