

Backflow Prevention Assembly Test and Maintenance Report

Name of PWS HAYS COUNTY WCID # Z				PWS I.D. # 1050	148	
PWS Mailing Address _ 14050 SUMMIT DRIVE SUITE 103 AUSTIN, TX 78728						
PWS Contact Person SCOTT MANUEL, MISSY ROBERTS, PHIL HENDERSON						
Address of Service 12395 MESA VERDE DR						
The backflow prevention assembly detailed below has been tested and maintained as required by TCEQ regulations and is certified to be operating within acceptable parameters.						
Type of Assembly Reduced Pressure Principle (RPBA) Double Check Valve (DCVA) Pressure Vacuum Breaker (PVB) Reduced Pressure Principle-Detector (RPBA-D) Double Check-Detector (DCVA-D) Spill-Resistant Pressure Vacuum Breaker (SVB)						
Manufacturer FE			Size 1			
3				BPA Location 10 W & METER		
Serial Number	HE 3421	5	BPA Serves	BPA Serves LANDSCAPE TRRIGATION		
Reason for Test: New Existing Replacement Old Model/Serial Number						
Is the assembly installed in accordance with manufacturer recommendations and/or local codes? 📓 Yes 🔲 No						
is the assembly installed on a non-potable water supply (auxiliary)?						
	Reduced Pressure Principle (RPI			PVB & SVB		
	Double Check	Valve (DCVA)	Relief Valve	Air Inlet	Check Valve	
	1 st Check	2 nd Check***	Neller valve	7 til lillot	Oncor valvo	
Initial Test Date: 040719 Time: 1670 Art		Held atpsid Closed Tight Leaked	Opened at psid	Opened at psid Did not open Did it fully open? Yes No	Held at psid	
Repairs and Materials Used**						
Test After Repair Date: Time:	Held at psid	Held at psid	Opened at psid	Opened at psid	Held atpsid	
*** 2 nd Check: Numeric reading required for DCVA only						
Differential Pressure Gauge Used Potable Non-Potable Make/Model MIDVIEST/845-3 Serial Number Collisid Date tested for accuracy D5/14/18 Remarks New E						
Company Name Inframark Licensed Tester Name (print/type)						
Company Address 14050 Summit Dr., Austin, TX 78728 Licensed Tester Name (signature)						
Company Phone 512-246-0498 BPAT License #BPCCCC2215 Expiration Date 02/12/2021						
		be true at the time o		Test R	esult	
	oe kept for at least thr turer's replacement pa	ee years [30 TAC §29 arts	U.40(B)]	Pass	☐ Fail	