

CITY OF LAGO VISTA

DEVELOPMENT SERVICES

5803 THUNDERBIRD SUITE 103 PO BOX 4727 LAGO VISTA, TX. 78645 Office: 512-267-5259 Fax: 512-267-5265

BACKFLOW PREVENTION ASSEMBLY TEST AND MAINTENANCE REPORT

		New Installation	☐ Annua	l Test	
	DDRESS: ACT PERSON:	DEVELOPMENT	AGO VISTA, TX 78 SERVICES	_	
		: HIGHLB 2317 HIDI	DEN SAGE	EGRUE	
The backflow prevention assembly detailed below has been tested and maintained as required by commission regulations and is certified to be operating within acceptable parameters.					
TYPE OF ASSEMBLY					
☐ Reduced Pressure Principle ☐ Double Check Valve ☐ Reduced Pressure Principle-Detector ☐ Pressure Vacuum Breaker ☐ Spill-Resistant Pressure Vacuum Breaker					
Manufacturer FEBCO Size 1" Model Number 850 Located At 6 NNW of METER Serial Number 11E 93581					
Is the assembly installed in accordance with manufacturer recommendations and/or local codes? YES					
	Reduced Pressure Principle Assembly			Pressure Vacuum Breaker	
	Double Check Valve Assembly			Air Inlet	
	1st Check	2nd Check	Relief Valve	Air Inlet	Check Valve
Initial Test	Held at Z zpsid Closed Tight Leaked	Held at Z. ensid Closed Tight A. Leaked	Opened at psid Did not open □	Opened at psid Did not open 🏻 🗆	Held at psid Leaked
Repairs and Materials Used			, 3.A.		
Test Aster Repair		Held at psid Closed Tight □	Opened at psid	Opened atpsid	Held at psid
Test gauge used: Make/Model 645-3 SN: O611314 Calibration Date: O4/29/19 Remarks: No. 16 The above is certified to be true at the time of testing. Firm Name: LSINGLAIR SERVICES Certified Tester.					
Firm Phone #: 512-563-8162 Cert. Tester No: 1300007811 Jate: 062115 Firm Address: CEDAR PARK TY 78613					