## Texas Commission on Environmental Quality BACKFLOW PREVENTION ASSEMBLY TEST AND MAINTENANCE REPORT

The following form must be c	ompleted for each			gned and date	d original must be submit	tted to	the public water supplier f	or recordkeepi	ng *purposes:	
NAME OF PWS:	City of Leander									
PWS ID#:	2460012									
PWS MAILING AD	PO Box 319 Leander, TX 78646									
PWS CONTACT PE	Christi Williams									
ADDRESS OF SERV	VICE:	2900 Wild Indigo Way y detailed below has been tested and maintained as required by commission regulations								
The backflow prevent	tion assemble	y detaile	ed below	has been	tested and maintain	nea a	as required by comin	iissioii ieg	uiations	
and is certified to be	operating wi	thin acc	eptable p	arameters	EXTENITION ACC	TC N/II	DI V (DDA).			
TYPE OF BACKFLOW PREVENTION ASSEMBLY (BPA):  Reduced Pressure Principle (RPBA) Reduced Pressure Principle-Detector (RPBA-D)										
			Double Check-Detector (DCVA-D)							
☐ Pressure Vacu	ıum Breakeı	(PVB)		Spill-I	Resistant Pressure	Vacu	ium Breaker (SVB)			
Manufacturer: I				Size:						
Model Number: 8				BPA Location:	9 E DE ME	METER				
Serial Number:	304			BPA Serves:	R	Residential Landscape Irrigation				
Reason for test: No	ew 🛛 E	existing		Replace	ement  Old Mo	odel/	/Serial #		10-10-10-10-10-10-10-10-10-10-10-10-10-1	
Is the assembly installed in accordance with manufacturer recommendations and/or local codes?								⊠ Yes	□No	
Is the assembly installed on a non-potable water supp								☐ Yes	⊠ No	
						DVIE.		ZINO		
TEST RESULT	Pressure Principle Assembly			⁄ (RPBA) ⊐l	RPBA)		PVB & SVB			
PASS 💆		DCVA			** Relief Valve		Air Inlet	Check Valve		
FAIL 1st C		heck 2 <sup>nd</sup> Check***					Air iiilet			
Initial Test Held at 7		7 psid Held at 2.7 psid			Opened at psid		Opened at	Held at	psid	
Date:		Tight Closed Tight			. 11		psid	Leaked		
Date: 070819 Time: 071084	Leaked	7	Leaked				Did not open			
0410171	Leaked		Leaked	LI						
							Did it fully open			
							(Yes □ /No □)			
Repairs and Materials				1.77000432						
Used**										
									20-0	
Test After Repair	Held at	psid Held at		neid	Opened at psic		Opened at	Held at psid		
Date:	Closed Tight  Closed			opened at poid		psid		post		
Time:	Closed 11g	3m 🗀	Closed	igiii 🗀			P			
	* 2nd check	numeric	reading	required f	or DCVA only					
Differential pressur			Todding		otable: 🛛		Non-Potable:	П		
					06111314 Date tested for accuracy: 04/29/19					
Make/Model: Mi	uwest / 843-	ر.	51	.   001	11314	שמו	ic residu for accurac	J. 104/2	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
Remarks: No	one									
									No distribution of the control of th	
		was a		2000	· · · · · · · · · · · · · · · · · · ·			-14-10-10-10-10-10-10-10-10-10-10-10-10-10-		
Company Name: L Since		ir Servic	ces Inc.	Licens	sed Tester Name	Lewis R. S	Sinclair			
1		331 13730 2007			Type):		~ A"	-01		
Company Address:	Cedar Pa	dar Park, TX 78613			sed Tester Name (S			X	الملة	
Company Phone #:	512-563-8762				License #	P0002815	1			
					se Expiration	02	2/12/2020			
				Date:						

The above is certified to be true at the time of testing.

\* TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS [30 TAC §290.46(B)]

\*\* USE ONLY MANUFACTURER'S REPLACEMENT PARTS