	AL TO
1	GEORGETOWN

Irrigation, Water and Wastewater Utility Cross Connection Section Test and Maintenance Report

000000000000000000000000000000000000000	-		
307	24	1	B
14	ب ال		
TERROR STREET			

*New Installa	ntion 🕱 Da	te: 072419 W	ater Meter #	NA Po	numais #	
**Annual Tes	t . O Day		W.C		ermit #	
Address: 70	ZI HAYS HILI	LDR.	Residential	Comm	Date: ercial O	
Owner/Busines	s Name: CENTUR	(LUMMUNITIE!	S Phone Num	her 517 - 77	1-3617	
Model Number	: 850 Size:	Device Location:	13'5 4 N	Serial N	Number HE 88	da
Manufacturer:	PEBLO	Reason de	vice is installed:	LERICATION	W/PEDBY	VIVE
RPDC_	PVB	SVB DCDA	RPDA	High Health: YES:	o No.	MA
	REDUCEDIP	RESSURE PRINCIPLE	ASSEMBLY	PRESSUREAVE	AGUUM BREAKERS	
	DOUBLECHE First check	Second check	Relief valve	Air relief	Check valve	88
INITIAL TEST	closed tight leaked p.s.i. Z	closed tight leaked	opened at	opened at	closed at	
	RPZ —	p.s.i. 28	p.s.i.d.	p.s.i.d.	p.s.i.d.	
	p.s.i.d.			Did not open □	Did not close □	
BACKFLOW STATUS (CIRCLE)	PASS	FAIL				
MATERIALS /		1742				
AND REPAIRS						
TEST AFTIER	closed tight p.s.i.	closed tight	opened at	opened at	closed at	
REPAIRS	p.s.i.d.	p.s.i	p.s.i.d.	p.s.i.d.		-
			p.o.t.u.	p.s.i.u.	p.s.i.d.	
I certify the abou	ve information to he tr	ue and correct to the be	est of sees less and a de			
Certified Tostor	occupant: CELTI	ARY COMMUNIT	Owner/Cont	tact: CENTURY	(SHIMMAN TIE	-5
Mailing address	(printed and signed	LEWIS R.S	PINGLAIR	Tuist	Turlas	
Tester Certif no	POINAG	ADO ROAD			10 -7 0	>
	mber: BPCC		Gauge Serial:			
Tester o priorie n	umber: <u>51'2-5</u>			r MIRUSMO	odel 245-3	
INSPECTION. Quest **ANNUAL /SEMI-A E-mail: customercare@	VAL REPORT MUST BE S tions, please call our office INNUAL TEST: City of Geo Degeorgetown.org or return this form within **TEST RI	Please forward this con ORIGINAL TEST FORM MUSIED INSPECTION. NEW INSUBMITTED TOGETHER WITH at (512) 930-2550 — Billing argetown Customer Care Center 10 business days of inspections MUST BE KEPT FOR CORNER 150 PROPERTY FOR THE PROPERTY OF	T BE PLACED IN THE TALLATIONS THAT AND QUESTIONS, please call (cer, 300-1 Industrial Avection may result in DR AT LEAST THREE	KE PAKI OF NEW CON IS INSPECTED DURING Customer Service at 512, re, P O Box 1430, George disconnection of wat YEARS**	ISTRUCTION FROM THE THE BUILDING FINAL 1930-3640. etown, Texas 78627.	
	TT*USE	ONLY MANUFACTURER'S	REPLACEMENT PAR	?T5***	1	