

Backflow Prevention Assembly Test Details



Test and Maintenance Report

Water System ID# 2270001

Special Services Division
3907 South Industrial DR
Austin, TX 78744-1070

Phone: (512) 972-1060
FAX: (512) 972-1260



*** Test records must be kept by the customer for at least three years ***

Backflow Assembly Information

Serial Number:	HE96673	Manufacturer:	FEBCO
Model:	850	Size:	1
Service Address:	2019 ASHBY AVE 78704		
Assembly location on the property:	8' SOUTH OF METER		
Reason the assembly is installed:	IRRIGATION W/ CITY POTABLE WATER		
Is this assembly installed to code requirements?	Yes		

Customer Information

Property Owner / Agent:	JOSEPH BUILDERS
Mailing Address:	1107 S 8TH STREET
City / State / Zip:	AUSTIN, TX 78704
Phone:	(512) 850-8974

Backflow Test

Initial Test	DCVA	
	Check Valve #1	Check Valve #2
	2.5 PSID	2.8 PSID

Repairs

Test After Repairs

Test Date:	Jul 29, 2019
Backflow Test Status:	Passed

Tester Information

The backflow technician listed below has previously certified that the information on this report was true and correct on the date of this test.

Backflow Technician:	SINCLAIR, LEWIS R
License:	BP0002815
Gauge Serial Number:	06111314