

## Backflow Prevention Assembly Test Details



## Test and Maintenance Report

Water System ID# 2270001

Special Services Division  
3907 South Industrial DR  
Austin, TX 78744-1070

Phone: (512) 972-1060  
FAX: (512) 972-1260



\*\*\* Test records must be kept by the customer for at least three years \*\*\*

## Backflow Assembly Information

Serial Number:	HE20012	Manufacturer:	FEBCO
Model:	850	Size:	3/4
Service Address:	917 W JAMES ST 78704		
Assembly location on the property:	4' SOUTH-SOUTHWEST OF METER.		
Reason the assembly is installed:	IRRIGATION W/ CITY POTABLE WATER		
Is this assembly installed to code requirements?	Yes		

## Customer Information

Property Owner / Agent:	JOSEPH BUILDERS
Mailing Address:	1107 S 8TH STREET
City / State / Zip:	AUSTIN, TX 78704
Phone:	(512) 850-8974

## Backflow Test

Initial Test	DCVA	
	Check Valve #1	Check Valve #2
	3.3 PSID	3.2 PSID

## Repairs

## Test After Repairs

Test Date:	Jul 25, 2019
Backflow Test Status:	Passed

## Tester Information

The backflow technician listed below has previously certified that the information on this report was true and correct on the date of this test.

Backflow Technician:	SINCLAIR, LEWIS R
License:	BP0002815
Gauge Serial Number:	06111314

## Backflow Prevention Assembly Test Details



## Test and Maintenance Report

Water System ID# 2270001

Special Services Division  
3907 South Industrial DR  
Austin, TX 78744-1070

Phone: (512) 972-1060  
FAX: (512) 972-1260



\*\*\* Test records must be kept by the customer for at least three years \*\*\*

## Backflow Assembly Information

Serial Number:	HE18943	Manufacturer:	FEBCO
Model:	850	Size:	3/4
Service Address:	917 W JAMES ST 78704		
Assembly location on the property:	8' SOUTHWEST OF METER.		
Reason the assembly is installed:	IRRIGATION W/ CITY POTABLE WATER		
Is this assembly installed to code requirements?	Yes		

## Customer Information

Property Owner / Agent:	JOSEPH BUILDERS
Mailing Address:	1107 S 8TH STREET
City / State / Zip:	AUSTIN, TX 78704
Phone:	(512) 850-8974

## Backflow Test

Initial Test	DCVA	
	Check Valve #1	Check Valve #2
	3.6 PSID	3.2 PSID

## Repairs

## Test After Repairs

Test Date:	Jul 26, 2019
Backflow Test Status:	Passed

## Tester Information

The backflow technician listed below has previously certified that the information on this report was true and correct on the date of this test.

Backflow Technician:	SINCLAIR, LEWIS R
License:	BP0002815
Gauge Serial Number:	06111314