

## **Backflow Prevention Assembly Test and Maintenance Report**

Name of PWS _ KE	LUNION F	PANCH		PWS I.D. #_15	050175
PWS Mailing Address	s 14050 SUMMIT D	RIVE SUITE 103 A	USTIN, TX 78728		
PWS Contact Persor	SCOTT MANUEL,	MISSY ROBERTS, P	HIL HENDERSON		
Address of Service _	2863 R	EUNION	BLVD.		
The backflow preven be operating within a			ted and maintained as red	quired by TCEQ re	gulations and is certified to
Double Check \	ure Principle (RPBA Valve (DCVA) um Breaker (PVB)		□ Double Check-l	ure Principle-Dete Detector (DCVA-D) Pressure Vacuum	
Manufacturer FEBCC Size					
Model Number	50		BPA Location	B WN 6	IMETER
Serial Number	E8410.	4	BPA Serves	NOSCAPE	IRRIGATION
Reason for Test:	New Exis	ting Replacem	•	4.8	
		ith manufacturer recon	nmendations and/or local	codes? XYes	□ No
Is the assembly insta	lled on a non-potable	water supply (auxiliar	y)?	☐ Yes	<b>№</b> No
	Red	Reduced Pressure Principle (RPBA)		PVB & SVB	
	Double Chec	k Valve (DCVA)	/alve (DCVA) Relief Valve		Check Valve
	1 <sup>st</sup> Check	2 <sup>nd</sup> Check***	Relief valve	Air Inlet	Gleck valve
Initial Test Date: Del Color Time: 1170 41	Held at <b>Z 2</b> psid <b>X</b> Closed Tight Leaked	Held at Z psid Closed Tight Leaked	Opened at psid Did not open	Opened at  Did not open Did it fully open?  Yes No	psid Held at psid Leaked
Repairs and Materials Used**					4.5
Test After Repair Date:	Held at psid	Held at psid	Opened at psid	Opened at	psid Held at psid
Differential Pressure Make/Model Miov Remarks No.	Gauge Used M	ric reading required fo		_ Date tested for	accuracy <u>04/79/19</u>
				3	
Company Name Infra			icensed Tester Name (pr	1 3	E SHUAIR
Company Address 14			icensed Tester Name (si		Towns In the second
Company Phone 512	-246-0498	E	BPAT License #BP 00	Expira CLUD	ation Date OLITE L
	e kept for at least thr	be true at the time of ee years [30 TAC §29] arts		Te Z Pass	est Result