

Backflow Prevention Assembly Test and Maintenance Report

Name of PWS	SUNION R	ANCH		PWS I.D. # 1050	175	
PWS Mailing Address	14050 SUMMIT DE	RIVE SUITE 103 AL	JSTIN, TX 78728			
PWS Contact Person	SCOTT MANUEL, I	MISSY ROBERTS, PH	HIL HENDERSON			
Address of Service _	441 KAT	IE DR.				
	tion assembly detailed		ed and maintained as rec	quired by TCEQ regulatio	ns and is certified to	
Double Check \	ure Principle (RPBA) Valve (DCVA) um Breaker (PVB)		☐ Double Check-I	ure Principle-Detector (R Detector (DCVA-D) Pressure Vacuum Breake	5.767	
Manufacturer FE	ecc		Size			
Model Number	50		BPA Location	7'SE OF N	ETER	
Serial Number HE37936 BPA Serves LANDSCAPE TRRICATION						
Reason for Test:	New Existi	ng Replacem	ent Old Model/Serial	Number H/A		
is the assembly insta			nmendations and/or local	codes? X Yes N	0	
Is the assembly installed on a non-potable water supply (auxiliary)?						
	Reduced Pressure Principle (RPI		e (RPBA)	PVB & SVB		
	Double Check	Valve (DCVA)	Relief Valve	Air Inlet	Check Valve	
	1 st Check	2 nd Check***	ivener valve	7 m mice	Griddin Valvo	
Initial Test Date: 091919 Time: 1050	Held at Z psid Closed Tight Leaked	Held at Z psid Closed Tight Leaked	Opened at psid	Opened at psid Did not open Did it fully open? Yes No	Held at psid	
Repairs and Materials Used**						
Test After Repair Date: Time:	Held at psid	Held atpsid	Opened at psid	Opened atpsid	Held atpsid	
	*** 2 nd Check: Nume	ric reading required fo	r DCVA only		J	
Differential Pressure Make/Model AID Remarks	151/245	Potable Non-Pota Serial Numb	able per ÖGİL İ 314	Date tested for accur	acy <u>04/79/19</u>	
Market Market Control of the Control						
Company Name Infr	amark		Licensed Tester Name (p	rint/type)	SHUAIR	
Company Address 1	4050 Summit Dr., Au			ed Tester Name (signature)		
Company Phone 512	2-246-0498		BPAT License #3700	Expiration D	ate OLIILICU	
		be true at the time o ee years [30 TAC §29		Test R	esult	
	turer's replacement pa		o. 14(D)1	✓ Pass	☐ Fail	