

CITY OF LAGO VISTA

DEVELOPMENT SERVICES

5803 THUNDERBIRD SUITE 103 PO BOX 4727 LAGO VISTA, TX. 78645 Office: 512-267-5259 Fax: 512-267-5265

BACKFLOW PREVENTION ASSEMBLY TEST AND MAINTENANCE REPORT

	X	New Installation		ıl Test	
NAME OF PWS: <u>CITY OF LAGO V</u>			/ISTA	•	
PWS I.D.: # <u>2270092</u>					
MAILING A	ADDRESS:	P.O. BOX 4727, L	AGO VISTA, TX 78	3645	
CITY CON	TACT PERSON:	DEVELOPMENT	SERVICES		
		3	: 1		
	OWNER'S NAME OF SERVICE: 7			DR-	
The backflor regulations a	w prevention assemb and is certified to be	oly detailed below h operating within ac	as been tested and m ceptable parameters.	aintained as required	by commission
8		TYL	PE OF ASSEMBLY		.58
☐ Reduced Pressure Principle ☐ Double Check-Detector ☐ Double Check-Detector ☐ Pressure Vacuum Breaker ☐ Spill-Resistant Pressure Vacuum Breaker					
Manufacture Model Numl Serial Numb	per 450		ocated At _ Zo N	NE RWE	FER
Is the assemi	bly installed in accor	dance with manufac	cturer recommendation	ons and/or local code	s? YES
	Reduced Pressure Principle Assembly			Pressure Vacuum Breaker	
	Double Check Valve Assembly				
	1st Check	2nd Check	Relief Valve	Air Inlet	Check Valve
nitial Test	Held at Z psid	Held at Z 9 psid	Opened at	Opened at	Held at psid
	Closed Tight	Closed Tight	psid	psid	Leaked \square
	Leaked D	Leaked 1	Did not open	Did not open	Dounted L
Repairs and Materials Jsed			,		
Test After Repair		Held at psid Closed Tight □	Opened at psid	Opened at psid	Held at psid
	M	IDWEST/	}	,)
Test gauge u Remarks:	sed: Make/Model		9#101	Calibration Da	ale: <u>84/29/19</u>
Firm Name:	certified to be true a	SERVICES	Certified Te		Luclis
Firm Phone # Firm Addres	The state of the s	- Annual Control of the Control of t	Cert. Tester	No: 13000075	13 ate: 09 1719