

Backflow Prevention Assembly Test Details



Test and Maintenance Report

Water System ID# 2270001

Special Services Division
3907 South Industrial DR
Austin, TX 78744-1070

Phone: (512) 972-1060
FAX: (512) 972-1260



*** Test records must be kept by the customer for at least three years ***

Backflow Assembly Information

| | | | |
|--|----------------------------------|---------------|-------|
| Serial Number: | HE97933 | Manufacturer: | FEBCO |
| Model: | 850 | Size: | 1 |
| Service Address: | 9706 BAYSHORE BND 78726 | | |
| Assembly location on the property: | 2' NORTH OF METER. | | |
| Reason the assembly is installed: | IRRIGATION W/ CITY POTABLE WATER | | |
| Is this assembly installed to code requirements? | Yes | | |

Customer Information

| | |
|-------------------------|----------------------------|
| Property Owner / Agent: | TAYLOR MORRISON HOMES |
| Mailing Address: | 11200 LAKELINE BLVD. #150A |
| City / State / Zip: | AUSTIN, TX 78717 |
| Phone: | (512) 328-8866 |

Backflow Test

| Initial Test | DCVA | |
|-----------------------|----------------|----------------|
| | Check Valve #1 | Check Valve #2 |
| | 0 PSID | 0 PSID |
| Repairs | | |
| Test After Repairs | 2.8 PSID | 2.7 PSID |
| Test Date: | Sep 26, 2019 | |
| Backflow Test Status: | Passed | |

Tester Information

The backflow technician listed below has previously certified that the information on this report was true and correct on the date of this test.

| | |
|----------------------|-------------------|
| Backflow Technician: | SINCLAIR, LEWIS R |
| License: | BP0002815 |
| Gauge Serial Number: | 06111314 |