

Backflow Prevention Assembly Test and Maintenance Report

Name of PWS RE	UNION R	ANCH		PWS I.D. # 1050	175
PWS Mailing Address	14050 SUMMIT DE	RIVE SUITE 103 AL	JSTIN, TX 78728		
PWS Contact Person	SCOTT MANUEL, N	MISSY ROBERTS, PH	HIL HENDERSON		
Address of Service	120 GLEN	MENT DR			
The backflow prevent be operating within ac	tion assembly detailed	below has been test	ed and maintained as rec	uired by TCEQ regulatio	ns and is certified to
Double Check \	ure Principle (RPBA) /alve (DCVA) um Breaker (PVB)		☐ Double Check-I	ure Principle-Detector (R Detector (DCVA-D) Pressure Vacuum Breake	
Manufacturer FE	30g		Size 1		
Model Number	50		BPA Location	7'WSWE	METER
Serial Number	F14635		BPA Serves	NOSCAPE IR	RIGATION
	New Existi	ng Replacem		4 3 2 -	
			nmendations and/or local	codes? Yes N	0
Is the assembly installed on a non-potable water supply (auxiliary)?					
	Reduced Pressure Principle		e (RPBA)	PVB & SVB	
	Double Check	Valve (DCVA)	Relief Valve	Air Inlet	Check Valve
	1st Check	2 nd Check***	Relief Valve	Air iniet	Olieck valve
Initial Test Date: 111019 Time: 1700P	Held at Zpsid Closed Tight Leaked	Held atpsid Closed Tight Leaked	Opened at psid Did not open	Opened at psid Did not open Did it fully open? Yes No	Held at psid
Repairs and Materials Used**					
Test After Repair Date: Time:	Held at psid	Held atpsid	Opened atpsid	Opened at psid	Held at psid
	*** 2 nd Check; Numer	ic reading required fo	r DCVA only	L	
Differential Pressure Make/Model	155/245	Potable Non-Pota Serial Numb	able per <u>CGIII3i4</u>	_ Date tested for accur	acy <u>64/29/</u> 19
					And the second s
Company Name Infra	amark	L	icensed Tester Name (p	rint/type) LEUIS R	SINCIAIRO,
Company Address 14	1050 Summit Dr., Au	stin, TX 78728	icensed Tester Name (si	gnature)	Timelas
Company Phone 512	-246-0498	E	BPAT License #BP & CO22 SExpiration Date 07/17/202		
	e kept for at least three	be true at the time of ee years [30 TAC §29 rts		Test Ro	esult