



4050 FM 1660 Hurst, Texas 78634 512-759-1286 Fax 512-759-2983

BACKFLOW PREVENTION ASSEMBLY TEST AND MAINTENANCE REPORT

PWS I.D: 2460022  
 MAILING ADDRESS 6032 TEODORO BEND  
 CONTACT PERSON TAYLOR MORRISON HOMES  
 LOCATION OF SERVICE 6032 TEODORO BEND  
 INSPECTION DATE 09/02/21

The backflow prevention assembly detailed below has been tested and maintained as required by TCEQ regulations and is certified to be operating within acceptable parameters.

TYPE OF ASSEMBLY

- Reduced Pressure Principle
- Double Check Valve
- Pressure Vacuum Breaker
- Reduced Pressure Principle-Detector
- Double Check-Detector
- Spill-Resistant Pressure Vacuum Breaker

Manufacturer: FEBCO

Model # B50 Serial # HFC3261

Location of device: 5' SSE OF METER

Is the assembly installed in accordance with manufacturer recommendations and/or local codes? YES

	Reduced Pressure Principle Assembly				Pressure Vacuum Breaker			
	Double Check Valve Assembly		Relief Valve		Air Inlet		Check Valve	
	1st Check	2nd Check			Opened at	psid	Held at	psid
Initial Test	Held at <u>2.5</u> psid	Held at <u>2.5</u> psid	Opened at	psid	Did not Open	<input type="checkbox"/>	Leaked	<input type="checkbox"/>
	Closed Tight <input checked="" type="checkbox"/>	Closed Tight <input checked="" type="checkbox"/>	Did not open	<input type="checkbox"/>				
	Leaked <input type="checkbox"/>	Leaked <input type="checkbox"/>						
Repairs and Materials Used								
Test After	Held at	psid	Held at	psid	Opened at	psid	Opened at	psid
Repair	Closed Tight	<input type="checkbox"/>	Closed Tight	<input type="checkbox"/>				

The above is certified to be true at the time of testing.

Test gauge used: Make / Model BACFLOW BACFLO-3 SN 03102474 Calibration Date: 4/01/21

Firm Name L SINCLAIR SERVICES Certified Tester [Signature]

Firm Address CEGAR PARK TX Cert. Tester No. BP0002815

Firm Phone # 512 563 8162

- TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS \*\* USE ONLY MANUFACTURER'S REPLACEMENT PARTS