



4050 FM 1660 Hutto, Texas 78634 512-759-1286 Fax 512-759-2983

BACKFLOW PREVENTION ASSEMBLY TEST AND MAINTENANCE REPORT

PWS I.D: 2460022
 MAILING ADDRESS 1002 Moose Rd, Hutto, TX, 78634
 CONTACT PERSON Home Owner
 LOCATION OF SERVICE 1002 Moose Rd, Hutto, TX, 78634
 INSPECTION DATE 11/12/2021

The backflow prevention assembly detailed below has been tested and maintained as required by TCEQ regulations and is certified to be operating within acceptable parameters.

TYPE OF ASSEMBLY

- Reduced Pressure ZONE
- Double Check Valve
- Pressure Vacuum Breaker
- Reduced Pressure Principle-Detector
- Double Check-Detector
- Spill-Resistant Pressure Vacuum Breaker

Manufacturer: Febco

Model # 850 Serial # 61276

Location of device : Front left yard - right of meter

Is the assembly installed in accordance with manufacturer recommendations and/or local codes? yes

	Reduced Pressure Principle Assembly				Pressure Vacuum Breaker		
	Double Check Valve Assembly		Relief Valve	Air Inlet		Check Valve	
	1st Check	2nd Check		Opened at	psid	Held at	psid
Initial Test	Held at <u>2.0</u> psid	Held at <u>2.2</u> psid	Opened at	psid	Did not Open <input type="checkbox"/>	Leaked <input type="checkbox"/>	
	Closed Tight <input checked="" type="checkbox"/> Leaked <input type="checkbox"/>	Closed Tight <input checked="" type="checkbox"/> Leaked <input type="checkbox"/>	Did not open	<input type="checkbox"/>			
Repairs and Materials Used							
Test After Repair	Held at <input type="checkbox"/> Closed Tight <input type="checkbox"/>	Held at <input type="checkbox"/> Closed Tight <input type="checkbox"/>	Opened at	psid	Opened at	psid	

The above is certified to be true at the time of testing,

Test gauge used: Make / Model Bac Flo 5 SN: 06163433 Calibration Date: 10/11/2021

Firm Name 1st Fire Safety Certified Tester Scott Stevenson

Firm Address PO Box 1238 Cedar Park, Tx 78613 Cert. Tester No. BP0017507

Firm Phone # 512-777-1555

- TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS ** USE ONLY MANUFACTURER'S REPLACEMENT PARTS