GEORGET ÖWN

Irrigation, Water and Wastewater Utility Cross Connection Section Test and Maintenance Report

| | - Company |
|-----|-----------|
| 143 | |
| 4 | >r |

| *New Installati | allation 🕱 Date: 17 67 21 Water Meter # | | | Permit # | | | |
|--|--|--|--|---|--|--|--|
| **Annual Test O Date: **Semi-Annual Test O Date: | | | | | | | |
| Address: 4379 MAYFIELD RONGH BLYD, Residential & Commercial O | | | | | | | |
| | SEAST CONTRACTOR OF THE PROPERTY OF THE PROPER | and Home | A STATE OF THE STA | | | ì | |
| | | Device Location: | | | | 157 | |
| Manufacturer: 1 | REBED | Reason des | rice is installed: [| IRRIGATION | PATABLE | JAR | |
| RP DC_ | | VB DCDA | | | | | |
| | REDUCEDIPR | essure principle | ASSEMBLY | PRESSUREVA | GUUMBREAKER! | The state of the s | |
| DOUBLECHECK ASSEMBLY | | | Relief valve | Air relief | Check valve | | |
| | First check | Second check | | | | 4 | |
| INITIAL TEST | closed tight leaked p.s.i. 2 | closed tight leaked | opened at | opened at | closed at | | |
| | 10,000 | p.s.i. 25 | p.s.i.d. | p.s.i.d. | p.s.i.d. | | |
| | RPZ p.s.i.d. | | 1 | Did not open □ | Did not close 🚨 | | |
| BACKELOW STATUS (CIRGLE) | PASS | FAIL | | | | | |
| MATERIALS AND REPAIRS | | | | | | | |
| TEST AFTIER | closed tight | closed tight | opened at | opened at | closed at | | |
| REPAIRS | _p.s.i RPZ p.s.i.d. | p.s.i | p.s.i.d. | p.s.i.d. | p.s.i.d. | | |
| | | | | | | | |
| I certify the abo | ve information to be t | rue and correct to the l | pest of my knowled | ige. | | 1 | |
| Property owner/occupant: HIGHLAND HOMESOwner/Contact: HIGHLAND HOMES | | | | | | | |
| Certified Tester | r: (printed and signe | d) Lewis R.S | Sinclair | A.zensk | Vinhal | | |
| Mailing addres | s: 1307 MAZ | HADO ROAL | | A 1805 A C | TX Zip: 7861 | 3 | |
| Tester Certif. n | umber: BPCC | 016/15 | 194762 | al: 03/62 | | | |
| Tester's phone | number: 512-5 | 563-8162 | Manufactu | reiUNLIMITEDIV | IodelBAC FLO | -3 | |
| ONLINE AT MYPER GROUND UP, ORIGI INSPECTION. QUI **ANNUAL /SEMI | MITNOW.ORG FOR REQU DINAL REPORT MUST BE estions, please call our offi MEANNUAL TEST: City of G | Please forward this of the property of the pro | IUST BE PLACED IN TE INSTALLATIONS THAT ITTH JOB PACKET AN Ing questions, please of | T ARE PART OF NEW CO ID IS INSPECTED DURI all Customer Service at 5 | <u>ONSTRUCTION FROM THI</u> I <u>NG THE BUILDING FINA</u> 12)930-3640. | <u>E</u> | |
| E-mail: customercar Failure | to return this form with **TEST | hin 10 business days of it RECORDS MUST BE KEPT ISE ONLY MANUFACTURE | TFOR AT LEAST THR | REE YEARS** | vater service, | | |