GEORGETÖÜNN

130P

Irrigation, Water and Wastewater Utility Cross Connection Section Test and Maintenance Report

New Installation Date: \[\begin{align} al				Permit #		
**Annual Test	O Date:	*>	Semi-Annual Te	est O D	ate:	
Address:	45 POST LE	XP	Residential ?	Commerc		
Owner/Business I	Name: TRI Pa	SINTE	Phone Number	er: 261-67	5-5100	- A
Model Number:	850_ Size:	Device Location:	Z'NE OF	MEIN Serial Nu	imber: 11 1 98	M
Manufacturer: F	EBCO	Reason dev	ice is installed: []	PRIGATION	PETABLE	JAR
RP DC	PVB S	VB DCDA	RPDA	High Health: YES: C	NO:	
	REDUCEDIPR	SSURE PRINCIPLE	ASSEMBLY =	PRESSURE VA	DUUM BREAKER	
	DOUBLECHECK ASSEMBLY		Relief valve	Air relief	Check valve	
	First check	Second check				
INITIAL TEST	closed tight leaked p.s.i.	closed tight leaked	opened at	opened at	closed at	
	p.s.i	p.s.i. 2,5	p.s.i.d.	p.s.i.d.	p.s.i.d.	
	RPZp.s.i.d.			Did not open 🛚	Did not close 🛛	
BACKELOW STATUS (GIRGUE)	PASS	FAIL				
NATERIALS AND REPAIRS		٠				
	closed tight	closed tight	opened at	opened at	closed at	
TEST AFTER REPAIRS	P.S.i RPZ p.s.i.d.	p.s.i	p.s.i.d.	p.s.i.d.	p.s.i.d.	
I certify the abo	l ve information to be l	true and correct to the	best of my knowled	dge.		
Property owner/occupant: TRI POINTE Owner/Contact: TRI POINTE						
Certified Tester: (printed and signed) LEWIS R. SINCLAIR						
Mailing addre	ss: 1307 MAZ	HADO ROAL	City: CEL	ARTAZ State:	TX Zip: 7561	3
	umber: BP		Gauge Seri		474	
Tester's phone	number: 51'2-	563-8162	Manufacti	reiliklini TED	Model BAC FLO	-3
* FOR ALL NEW II ONLINE AT MYPE GROUND UP, ORI INSPECTION. QU **ANNUAL /SEM	VSTALLATIONS, COMPLETI RMITNOW.ORG FOR REOL GINAL REPORT MUST BE JUDITION OF BE J		INSTALLATIONS THAN WITH JOB PACKET AI Ing questions, please of Center, 300-1 Industria Inspection may resu	TAIL TAIL TAIL TAIL TAIL TAIL TAIL TAIL	ING THE BUILDING FINA 512)930-3640. orgetown, Texas 78627.	