

4050 FM 1660 Hutto, Texas 78634

512-759-1286 Fax 512-759-

PWS I.D: 2460022	KFLOW PREVENTI				
CONTACT PERSON					
LOCATION OF SERV	VICE_506 Stinchcomb R				
INSPECTION DATE	12/8/2021 6:00PM				
	tion assembly detailed l		ed and maintained as r	equired by TCEQ regula	ations and
		TYPE OF	ASSEMBLY		
() Reduced Pressure ZONE () Reduced Pre				Principle-Detector	
(X) Double Check Valve			() Double Check-Detector		
() Press	ure Vacuum Breaker		() Spill-Resistant I	Pressure Vacuum Brea	ker
Manufactur	er: Febco				
Model # 85	0	_ Serial # HF9844	0		
Location of	device Left front yard	near meter			
Is the assembly insta	illed in accordance with	manufacturer recom	mendations and/or loc	al codes? Yes	
	Reduced	Pressure Principle A	ssembly	nbly Pressure Vacuum Breaker	
	Double Check Valve	e Assembly	Relief Valve	Air Inlet	Check Valve
	1st Check	2nd Check		Opened at psid	Held at psid
Initial Test	Held at 2.3 psid	Held at 2.2 psid	Opened at psid	Did not Open □	Leaked
	Closed Tight X Leaked □	Closed Tight X Leaked	Did not open □		
Repairs and Materials Used					
Test After	Held at psid Closed Tight □	Held at psid Closed Tight □	Opened at psid	Opened at psid	Held At psid
Repair					
The above is certifi	ied to be true at the time	e of testing,			
Test gauge used: N	Make / Model Mid West	: 845 SN: 10	150482 Calib	ration Date:10/7/2021	
Firm Name Safewater Backflow			Certified Tester: Brad Weyant		
Firm Address PO	Box 4002 Austin, TX 7	8765	Cert. Tester No	BP0016935	
Firm Phone # 512	2-605-9790				

- TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS ** USE ONLY MANUFACTURER'S REPLACEMENT PARTS